



OIL ANALYSIS REPORT

WEAR	NORMAL
CONTAMINATION	ABNORMAL
FLUID CONDITION	NORMAL

Machine Id
190 CLARK
 Component
Diesel Engine
 Fluid
MOBIL DELVAC 1200 SP15W40 (24 LTR)

RECOMMENDATION

NOTE: The bottle submitted did not contain sample for testing.

Test	UOM	Method	Limit/Abn	Current	History1	History2
Sample Number		Client Info		WC0824612	WC0443228	WC773206
Sample Date		Client Info		07 Sep 2023	26 May 2020	06 Aug 2008
Machine Age	hrs	Client Info		0	0	343
Oil Age	hrs	Client Info		0	0	0
Filter Age	hrs	Client Info		0	0	0
Oil Changed		Client Info		N/A	N/A	Changed
Filter Changed		Client Info		N/A	N/A	Not Changd
Sample Status				ABNORMAL	NORMAL	NORMAL

WEAR

{not applicable}

White Metal	scalar	Visual*	NONE	NONE	---	---
Yellow Metal	scalar	Visual*	NONE	NONE	---	---

CONTAMINATION

{not applicable}

Fuel		WC Method	>5	<1.0	<1.0	1.0
Water		WC Method	>0.2	NEG	NEG	NEG
Glycol		WC Method		NEG	NEG	NEG
Silt	scalar	Visual*	NONE	NONE	---	---
Debris	scalar	Visual*	NONE	NONE	---	---
Sand/Dirt	scalar	Visual*	NONE	NONE	---	---
Appearance	scalar	Visual*	NORML	▲ NOOIL	---	---
Odor	scalar	Visual*	NORML	NORML	---	---



Laboratory : WearCheck - C8-1175 Appleby Line, Burlington, ON L7L 5H9
Sample No. : WC0824612
Lab Number : 02643308
Unique Number : 5800847
Test Package : TEST

Received : 20 Jun 2024
Tested : 21 Jun 2024
Diagnosed : 21 Jun 2024 - Kevin Marson

NORTHERN GENERATOR CO. LTD.
80 ASHBRIDGE CIRCLE,, UNIT #1 & 2
WOODBIDGE, ON
CA L4L 3R5

Contact: Selome Afework
selome@northerngenerator.com

T: (905)264-9744
F: (905)264-9714

To discuss this sample report, contact Customer Service at 1-800-268-2131.

Test denoted (*) outside scope of accreditation, (m) method modified, (e) tested at external lab.

Validity of results and interpretation are based on the sample and information as supplied.