



OIL ANALYSIS REPORT

WEAR	NORMAL
CONTAMINATION	ABNORMAL
FLUID CONDITION	NORMAL

Machine Id
1185 CALEDONIA
 Component
Diesel Engine
 Fluid
MOBIL DELVAC 1300 SUPER15W40 (--- LTR)

RECOMMENDATION

NOTE: The bottle submitted did not contain sample for testing.

Test	UOM	Method	Limit/Abn	Current	History1	History2
Sample Number		Client Info		WC0884759	WC0313569	---
Sample Date		Client Info		22 Jan 2024	10 Jul 2019	---
Machine Age	hrs	Client Info		0	0	---
Oil Age	hrs	Client Info		0	0	---
Filter Age	hrs	Client Info		0	0	---
Oil Changed		Client Info		N/A	Changed	---
Filter Changed		Client Info		N/A	Changed	---
Sample Status				ABNORMAL	SEVERE	---

WEAR


{not applicable}

White Metal	scalar	Visual*	NONE	NONE	VLITE	---
Yellow Metal	scalar	Visual*	NONE	NONE	NONE	---

CONTAMINATION

{not applicable}

Fuel		WC Method	>5	<1.0	0.2	---
Water		WC Method	>0.2	NEG	NEG	---
Glycol	%	ASTM D7922*		NEG	▲ 0.10	---
Silt	scalar	Visual*	NONE	NONE	NONE	---
Debris	scalar	Visual*	NONE	NONE	VLITE	---
Sand/Dirt	scalar	Visual*	NONE	NONE	NONE	---
Appearance	scalar	Visual*	NORML	▲ NOOIL	NORML	---
Odor	scalar	Visual*	NORML	NORML	NORML	---



Laboratory : WearCheck - C8-1175 Appleby Line, Burlington, ON L7L 5H9
Sample No. : WC0884759
Lab Number : 02643309
Unique Number : 5800848
Test Package : TEST

NORTHERN GENERATOR CO. LTD.
 80 ASHBRIDGE CIRCLE., UNIT #1 & 2
 WOODBRIDGE, ON
 CA L4L 3R5

Received : 20 Jun 2024
Tested : 21 Jun 2024
Diagnosed : 21 Jun 2024 - Kevin Marson

Contact: Selome Afework
 selome@northerngenerator.com

To discuss this sample report, contact Customer Service at 1-800-268-2131.
 Test denoted (*) outside scope of accreditation, (m) method modified, (e) tested at external lab.
 Validity of results and interpretation are based on the sample and information as supplied.

T: (905)264-9744
 F: (905)264-9714