**WEAR CONTAMINATION FLUID CONDITION** 

**ABNORMAL NORMAL NORMAL** 

## Blythe & Zachary JV CSA - I85 SC [7162] VOLVO SD115B 4203212 (S/N 236330)

Component

Left Final Drive VOLVO ( GAL)							
RECOMMENDATION	Test	UOM	Method	Limit/Abn	Current	History1	History2
No corrective action is recommended at this time. Resample at the next service interval to monitor.	Sample Number		Client Info		VCP147696		
	Sample Date		Client Info		01 Apr 2019		
	Machine Age		Client Info		500		
	Oil Age		Client Info		0		
	Filter Age		Client Info		0		
	Oil Changed		Client Info		Not Changd		
	Filter Changed		Client Info		Not Changd		
	Sample Status				ABNORMAL		
WEAR	Iron	ppm	ASTM D5185m	>500	99		
High concentration of visible metal present. Metal levels are typical for a new component breaking in.	Chromium	ppm	ASTM D5185m		1		
	Nickel	ppm	ASTM D5185m		- <1		
	Titanium	ppm	ASTM D5185m		<1		
	Silver	ppm	ASTM D5185m		0		
	Aluminum	ppm	ASTM D5185m	>25	<1		
	Lead	ppm	ASTM D5185m	>25	0		
	Copper	ppm	ASTM D5185m	>50	<1		
	Tin	ppm	ASTM D5185m	>10	0		
	Vanadium	ppm	ASTM D5185m		0		
	White Metal	scalar	*Visual	NONE	▲ HEAVY		
	Yellow Metal	scalar	*Visual	NONE	NONE		
CONTAMINATION	Silicon	ppm	ASTM D5185m	>75	9		
There is no indication of any contamination in the oil.	Potassium	ppm	ASTM D5185m	>20	<1		
	Water		WC Method	>0.2	NEG		
	Silt	scalar	*Visual	NONE	NONE		
	Debris	scalar	*Visual	NONE	NONE		
	Sand/Dirt	scalar	*Visual	NONE	NONE		
	Appearance	scalar	*Visual	NORML	NORML		
	Odor	scalar	*Visual	NORML	NORML		
	Emulsified Water	scalar	*Visual	>0.2	NEG		
FLUID CONDITION	Sodium	ppm	ASTM D5185m		3		
The condition of the oil is acceptable for the time in service.	Boron	ppm	ASTM D5185m		123		
	Barium	ppm	ASTM D5185m		3		
	Molybdenum	ppm	ASTM D5185m		<1		
	Manganese	ppm	ASTM D5185m		3		
	Magnesium	ppm	ASTM D5185m		7		
	Calcium	ppm	ASTM D5185m		80		
	Phosphorus	ppm	ASTM D5185m		833		
	Zinc	ppm	ASTM D5185m		119		
	Sulfur	ppm	ASTM D5185m		19558		
	Visc @ 40°C	cSt	ASTM D445		137		





Certificate L2367

Laboratory Sample No.

: VCP147696 Lab Number : 04709518 Unique Number: 8591062 Test Package : MOB 1

: WearCheck USA - 501 Madison Ave., Cary, NC 27513 Received : 08 May 2019 **Tested** : 09 May 2019

: 09 May 2019 - Don Baldridge Diagnosed

**BLYTHE CONSTRUCTION INC** 

2911 N GRAHAM STREET CHARLOTTE, NC US 28231

Contact: Service Manager

To discuss this sample report, contact Customer Service at 1-800-237-1369.

\* - Denotes test methods that are outside of the ISO 17025 scope of accreditation.

Statements of conformity to specifications are based on the simple acceptance decision rule (JCGM 106:2012)

F: (704)373-2960