
**WEAR CONTAMINATION FLUID CONDITION**  **NORMAL NORMAL NORMAL** 

**PAUL JOHNSON [7710072] VOLVO PENTA A583186** 

Port Diesel Engine

VOLVO PENTA SAE 15W40 (5 GAL)							
RECOMMENDATION	Test	UOM	Method	Limit/Abn	Current	History1	History2
Resample at the next service interval to monitor.	Sample Number		Client Info		VPA029135		
	Sample Date		Client Info		30 Jul 2020		
	Machine Age	hrs	Client Info		220		
	Oil Age	hrs	Client Info		40		
	Filter Age	hrs	Client Info		0		
	Oil Changed		Client Info		Not Changd		
	Filter Changed		Client Info		Not Changd		
	Sample Status				NORMAL		
WEAR	Iron	ppm	ASTM D5185m	>80	9		
All component wear rates are normal.	Chromium	ppm	ASTM D5185m	>6	<1		
	Nickel	ppm	ASTM D5185m	>2	1		
	Titanium	ppm	ASTM D5185m	>2	<1		
	Silver	ppm	ASTM D5185m	>2	0		
	Aluminum	ppm	ASTM D5185m	>20	2		
	Lead	ppm	ASTM D5185m	>95	1		
	Copper	ppm	ASTM D5185m	>85	4		
	Tin	ppm	ASTM D5185m	>9	0		
	Vanadium	ppm	ASTM D5185m		0		
	White Metal	scalar	*Visual	NONE	NONE		
	Yellow Metal	scalar	*Visual	NONE	NONE		
CONTAMINATION	Silicon	ppm	ASTM D5185m	>25	7		
	Potassium	ppm	ASTM D5185m	>20	8		
There is no indication of any contamination in the oil.	Fuel		WC Method	>4.0	<1.0		
	Water		WC Method	>0.1	NEG		
	Glycol		WC Method		NEG		
	Soot %	%	*ASTM D7844		0.1		
	Nitration	Abs/cm	*ASTM D7624	>20	5.2		
	Sulfation	Abs/.1mm	*ASTM D7415	>30	18.7		
	Silt	scalar	*Visual	NONE	NONE		
	Debris	scalar	*Visual	NONE	NONE		
	Sand/Dirt	scalar	*Visual	NONE	NONE		
	Appearance	scalar	*Visual	NORML	NORML		
	Odor	scalar	*Visual	NORML	NORML		
	Emulsified Water	scalar	*Visual	>0.1	NEG		
FLUID CONDITION  The BN result indicates that there is suitable alkalinity remaining in the oil. The condition of the oil is suitable for further service.	Sodium	ppm	ASTM D5185m		2		
	Boron	ppm	ASTM D5185m		4		
	Barium	ppm	ASTM D5185m		0		
	Molybdenum	ppm	ASTM D5185m		60		
	Manganese	ppm	ASTM D5185m		<1		
	Magnesium	ppm	ASTM D5185m		1034		
	Calcium	ppm	ASTM D5185m		1103		
	Phosphorus	ppm	ASTM D5185m		1034		
	Zinc	ppm	ASTM D5185m		1172		
	Sulfur	ppm	ASTM D5185m		2730		
	Oxidation	Abs/.1mm	*ASTM D7414	>25	13.8		
	Visc @ 100°C	cSt	ASTM D445		13.3		





Certificate L2367

Laboratory Sample No.

: VPA029135 Lab Number : 05040100 Unique Number : 9130270 Test Package : MOB 1

: WearCheck USA - 501 Madison Ave., Cary, NC 27513 Received : 10 Aug 2020 **Tested** : 12 Aug 2020

: 12 Aug 2020 - Angela Borella Diagnosed

Pacific Power Group - VP981534 7215 S 228th St Kent, WA

US 98032 Contact: STEVE CAREY scarey@pacificpowergroup.com

T: (253)740-0842

F: x:

To discuss this sample report, contact Customer Service at 1-800-237-1369. \* - Denotes test methods that are outside of the ISO 17025 scope of accreditation.

Statements of conformity to specifications are based on the simple acceptance decision rule (JCGM 106:2012)

Contact/Location: STEVE CAREY - VP99031103