

Blythe & Zachary JV CSA - 185 SC VOLVO SD115B 4203215 (S/N 236408)

Component Drum Carrier Bearing

{not provided} (--- GAL)

RECOMMENDATION

No corrective action is recommended at this time. Resample at the next service interval to monitor.

V	V	E,	Α	R

Δro

The lead level is abnormal. All other component wear rates are normal.

CONTAMINATION

There is no indication of any contamination in the oil.

FLUID CONDITION

The condition of the oil is acceptable for the time in service.

Test	UOM	Method	Limit/Abn	Current	History1	History2
Sample Number		Client Info		VCP287834		
Sample Date		Client Info		29 Oct 2020		
Machine Age		Client Info		0		
Oil Age		Client Info		0		
Filter Age		Client Info		0		
Oil Changed		Client Info		N/A		
Filter Changed		Client Info		N/A		
Sample Status				ABNORMAL		
Iron	ppm	ASTM D5185m	>200	140		
Chromium	ppm	ASTM D5185m	>10	2		
Nickel	ppm	ASTM D5185m		<1		
Titanium	ppm	ASTM D5185m		0		
Silver	ppm	ASTM D5185m		<1		
Aluminum	ppm	ASTM D5185m	>25	<1		
Lead	ppm	ASTM D5185m	>50	1 43		
Copper	ppm	ASTM D5185m	>200	29		
Tin	ppm	ASTM D5185m	>10	<1		
Vanadium	ppm	ASTM D5185m		0		
White Metal	scalar	*Visual	NONE	NONE		
Yellow Metal	scalar	*Visual	NONE	NONE		
Silicon	ppm	ASTM D5185m	>50	20		
Potassium	ppm	ASTM D5185m	>20	35		
Water	ppiii	WC Method	>0.2	NEG		
			, o.=			
Silt	scalar	*Visual	NONE	NONE		
Silt Debris	scalar scalar	*Visual	NONE	NONE		
Debris	scalar	*Visual	NONE	NONE		
Debris Sand/Dirt	scalar scalar	*Visual *Visual	NONE	NONE		
Debris Sand/Dirt Appearance	scalar scalar scalar	*Visual *Visual *Visual	NONE NONE NORML	NONE NONE NORML		
Debris Sand/Dirt Appearance Odor	scalar scalar scalar scalar	*Visual *Visual *Visual *Visual	NONE NORML NORML	NONE NONE NORML NORML		
Debris Sand/Dirt Appearance	scalar scalar scalar	*Visual *Visual *Visual	NONE NONE NORML	NONE NONE NORML		
Debris Sand/Dirt Appearance Odor	scalar scalar scalar scalar	*Visual *Visual *Visual *Visual	NONE NORML NORML	NONE NONE NORML NORML		
Debris Sand/Dirt Appearance Odor Emulsified Water	scalar scalar scalar scalar scalar	*Visual *Visual *Visual *Visual *Visual	NONE NORML NORML	NONE NORML NORML NEG		
Debris Sand/Dirt Appearance Odor Emulsified Water Sodium	scalar scalar scalar scalar scalar ppm	*Visual *Visual *Visual *Visual *Visual ASTM D5185m	NONE NORML NORML	NONE NORML NORML NEG 7		
Debris Sand/Dirt Appearance Odor Emulsified Water Sodium Boron	scalar scalar scalar scalar scalar ppm ppm	*Visual *Visual *Visual *Visual *Visual ASTM D5185m	NONE NORML NORML	NONE NORML NORML NEG 7 9		
Debris Sand/Dirt Appearance Odor Emulsified Water Sodium Boron Barium	scalar scalar scalar scalar scalar ppm ppm	*Visual *Visual *Visual *Visual *Visual ASTM D5185m ASTM D5185m	NONE NORML NORML	NONE NORML NORML NEG 7 9 0		
Debris Sand/Dirt Appearance Odor Emulsified Water Sodium Boron Barium Molybdenum	scalar scalar scalar scalar scalar ppm ppm ppm	*Visual *Visual *Visual *Visual *Visual ASTM D5185m ASTM D5185m ASTM D5185m	NONE NORML NORML	NONE NORML NORML NEG 7 9 0 <1		
Debris Sand/Dirt Appearance Odor Emulsified Water Sodium Boron Barium Molybdenum Manganese	scalar scalar scalar scalar scalar ppm ppm ppm ppm	*Visual *Visual *Visual *Visual *Visual ASTM D5185m ASTM D5185m ASTM D5185m ASTM D5185m	NONE NORML NORML	NONE NORML NORML NEG 7 9 0 <1 2		
Debris Sand/Dirt Appearance Odor Emulsified Water Sodium Boron Barium Molybdenum Manganese Magnesium	scalar scalar scalar scalar ppm ppm ppm ppm ppm	*Visual *Visual *Visual *Visual *Visual ASTM D5185m ASTM D5185m ASTM D5185m ASTM D5185m ASTM D5185m	NONE NORML NORML	NONE NORML NORML NEG 7 9 0 <1 2 1		
Debris Sand/Dirt Appearance Odor Emulsified Water Sodium Boron Barium Molybdenum Manganese Magnesium Calcium	scalar scalar scalar scalar ppm ppm ppm ppm ppm ppm	*Visual *Visual *Visual *Visual *Visual ASTM D5185m ASTM D5185m ASTM D5185m ASTM D5185m ASTM D5185m ASTM D5185m	NONE NORML NORML	NONE NORML NORML NEG 7 9 0 <1 2 1 1 11		


Visc @ 40°C


cSt

ASTM D445

Contact/Location: TRAVIS TURNAGE - AYDSTA

203





BLYTHE CONSTRUCTION INC Laboratory : WearCheck USA - 501 Madison Ave., Cary, NC 27513 Sample No. Received 2911 N GRAHAM STREET : VCP287834 : 03 Nov 2020 Lab Number : 05106577 CHARLOTTE, NC Tested :04 Nov 2020 Unique Number : 9241836 : 05 Nov 2020 - Don Baldridge US 28231 Diagnosed Test Package : MOB 1 Contact: TRAVIS TURNAGE Certificate L2367 To discuss this sample report, contact Customer Service at 1-800-237-1369. travisturnage@gmail.com * - Denotes test methods that are outside of the ISO 17025 scope of accreditation. Т: Statements of conformity to specifications are based on the simple acceptance decision rule (JCGM 106:2012) F: (704)373-2960

Contact/Location: TRAVIS TURNAGE - AYDSTA

Page 2 of 2