WEAR CONTAMINATION FLUID CONDITION

NORMAL NORMAL

Area

Ascendum Machinery VOLVO A45G PN-1 (S/N 342225)

Component Drop Box

DECOMMENDATION.	_				/ <u> </u>	\	
RECOMMENDATION	Test	UOM	Method	Limit/Abn	Current	History1	History2
Resample at the next service interval to monitor.	Sample Number		Client Info		VCP335324		
	Sample Date		Client Info		11 Nov 2021		
	Machine Age	hrs	Client Info		0		
	Oil Age	hrs	Client Info		0		
	Filter Age	hrs	Client Info		0		
	Oil Changed		Client Info		N/A		
	Filter Changed		Client Info		N/A NORMAL		
	Sample Status				NORMAL		
WEAR	Iron	ppm	ASTM D5185m	>500	108		
All component wear rates are normal.	Chromium	ppm	ASTM D5185m	>20	1		
	Nickel	ppm	ASTM D5185m	>10	0		
	Titanium	ppm	ASTM D5185m		0		
	Silver	ppm	ASTM D5185m		0		
	Aluminum	ppm	ASTM D5185m	>30	8		
	Lead	ppm	ASTM D5185m	>30	0		
	Copper	ppm	ASTM D5185m	>30	1		
	Tin	ppm	ASTM D5185m	>20	0		
	Vanadium	ppm	ASTM D5185m		0		
	White Metal	scalar	*Visual	NONE	VLITE		
	Yellow Metal	scalar	*Visual	NONE	NONE		
CONTAMINATION	Silicon	nnm	ASTM D5185m	>50	16		
	Potassium	ppm	ASTM D5185m		0		
There is no indication of any contamination in the oil.	Water	ppm	WC Method	>0.2	NEG		
	Silt	scalar	*Visual	NONE	NONE		
	Debris	scalar	*Visual	NONE	NONE		
	Sand/Dirt	scalar	*Visual	NONE	NONE		
	Appearance	scalar	*Visual	NORML	NORML		
	Odor	scalar	*Visual	NORML	NORML		
	Emulsified Water	scalar	*Visual	>0.2	NEG		
FLUID CONDITION	Sodium	ppm	ASTM D5185m		2		
The condition of the oil is acceptable for the time in service.	Boron	ppm	ASTM D5185m		33		
	Barium	ppm	ASTM D5185m		0		
	Molybdenum	ppm	ASTM D5185m		2		
	Manganese	ppm	ASTM D5185m		1		
	Magnesium	ppm	ASTM D5185m		0		
	Calcium	ppm	ASTM D5185m		483		
	Phosphorus	ppm	ASTM D5185m		592		
	Zinc	ppm	ASTM D5185m		96		
	Sulfur	ppm	ASTM D5185m		23912		
	Visc @ 40°C	cSt	ASTM D445		196		







Certificate L2367

Laboratory Sample No.

: VCP335324 Lab Number : 05400001 Unique Number : 9739151 Test Package : MOB 1

: WearCheck USA - 501 Madison Ave., Cary, NC 27513 Received : 12 Nov 2021 : 16 Nov 2021 **Tested**

: 16 Nov 2021 - Don Baldridge Diagnosed

CAROLINA EXCAVATING

1036 BRANCHVIEW DR, SUITE 106 CONCORD, NC

US 28025

Contact: KEVIN LADGERWOOD kevin@carlinaexcavation.com

To discuss this sample report, contact Customer Service at 1-800-237-1369.

T:

* - Denotes test methods that are outside of the ISO 17025 scope of accreditation. Statements of conformity to specifications are based on the simple acceptance decision rule (JCGM 106:2012)

Report Id: CARCONVC [WUSCAR] 05400001 (Generated: 03/01/2024 13:01:18) Rev: 1

Contact/Location: KEVIN LADGERWOOD - CARCONVC

F: