
**WEAR** CONTAMINATION **FLUID CONDITION** 

**NORMAL ABNORMAL NORMAL** 

## MATTEI 10009100-2019 - ASU-211

Component Compressor

ROTOROIL 8000 (2 QTS)							
RECOMMENDATION	Test	UOM	Method	Limit/Abn	Current	History1	History2
No corrective action is recommended at this time. The oil change at the time of sampling has been noted. Resample at the next service interval to monitor.	Sample Number		Client Info		AN38891		
	Sample Date		Client Info		19 Dec 2022		
	Machine Age	hrs	Client Info		1950		
	Oil Age	hrs	Client Info		0		
	Filter Age	hrs	Client Info		0		
	Oil Changed		Client Info		Changed		
	Filter Changed		Client Info		N/A		
	Sample Status				ABNORMAL		
WEAR	Iron	ppm	ASTM D5185m	>50	4		
All component wear rates are normal.	Chromium	ppm	ASTM D5185m	>10	0		
	Nickel	ppm	ASTM D5185m		0		
	Titanium	ppm	ASTM D5185m		0		
	Silver	ppm	ASTM D5185m		0		
	Aluminum	ppm	ASTM D5185m	>25	0		
	Lead	ppm	ASTM D5185m	>25	0		
	Copper	ppm	ASTM D5185m	>50	<1		
	Tin	ppm	ASTM D5185m	>15	0		
	Vanadium	ppm	ASTM D5185m		0		
	White Metal	scalar	*Visual	NONE	LIGHT		
	Yellow Metal	scalar	*Visual	NONE	NONE		
CONTANINATION	0.11.		AOTA DE LOS	05			
CONTAMINATION  Elemental level of silicon (Si) above normal indicating ingress of seal material.	Silicon	ppm	ASTM D5185m		<u>42</u>		
	Potassium Water	ppm	ASTM D5185m ASTM D6304		1 0.054		
		%		>0.1	0.051		
	ppm Water Silt	ppm	*Visual	>1000 NONE	518.7 NONE		
	Debris	scalar	*Visual	NONE	NONE		
	Sand/Dirt	scalar scalar	*Visual	NONE	NONE		
	Appearance	scalar	*Visual	NORML	NORML		
	Odor	scalar	*Visual	NORML	NORML		
	Emulsified Water		*Visual	>0.1	NEG		
FLUID CONDITION	Sodium	ppm	ASTM D5185m		0		
The AN level is acceptable for this fluid.	Boron	ppm	ASTM D5185m		0		
	Barium	ppm	ASTM D5185m		0		
	Molybdenum	ppm	ASTM D5185m		0		
	Manganese	ppm	ASTM D5185m		0		
	Magnesium	ppm	ASTM D5185m		<1		
	Calcium	ppm	ASTM D5185m		0		
	Phosphorus	ppm	ASTM D5185m	884	1145		
	Zinc	ppm	ASTM D5185m		7		
	Sulfur	ppm	ASTM D5185m		84		
	Acid Number (AN)	mg KOH/g	ASTM D8045		0.23		
	Visc @ 40°C	cSt	ASTM D445		78.7		
Report Id: MATTFI [WUSCAR] 05744211 (Generated: 01/22/2024 12:08:48) Rev: 1				Contact	/Location: M	ARTY WAR	I) - MATTEL







Certificate L2367

Laboratory Sample No. Lab Number **Unique Number** 

: AN38891 : 05744211 : 10298810 Test Package : IND 2

: WearCheck USA - 501 Madison Ave., Cary, NC 27513 Recieved : 19 Jan 2023 Diagnosed : 20 Jan 2023 Diagnostician : Doug Bogart

To discuss this sample report, contact Customer Service at 1-800-237-1369.

\* - Denotes test methods that are outside of the ISO 17025 scope of accreditation. Statements of conformity to specifications are based on the simple acceptance decision rule (JCGM 106:2012)

MATTEI COMPRESSORS--OEM

9635 LIBERTY ROAD, SUITE E RANDALLSTOWN, MD US 21133

Contact: MARTY WARD jward@matteicomp.com

> T: (410)521-7020 F: (410)521-7024