**WEAR** CONTAMINATION **FLUID CONDITION**  **ABNORMAL ATTENTION NORMAL** 

Machine Id TK22689

Component Hydraulic System

ECOMMENDATION	Test	UOM	Method	Limit/Abn	Current	History1	History2
No corrective action is recommended at this time. December at the	Sample Number		Client Info		WC0708506	WC0636284	
No corrective action is recommended at this time. Resample at the next service interval to monitor.	Sample Date		Client Info		25 Jan 2023		
	Machine Age	hrs	Client Info		0	0	
	Oil Age	hrs	Client Info		0	0	
	Filter Age	hrs	Client Info		0	0	
	Oil Changed		Client Info		N/A	N/A	
	Filter Changed		Client Info		N/A	N/A	
	Sample Status				ABNORMAL	ABNORMAL	
WEAR	Iron	ppm	ASTM D5185m	>20	14	14	
	Chromium	ppm	ASTM D5185m	>10	1	1	
The copper level is abnormal. All other component wear rates are normal.	Nickel	ppm	ASTM D5185m	>10	0	0	
	Titanium	ppm	ASTM D5185m		<1	<1	
	Silver	ppm	ASTM D5185m		0	0	
	Aluminum	ppm	ASTM D5185m	>10	0	<1	
	Lead	ppm	ASTM D5185m	>10	<1	0	
	Copper	ppm	ASTM D5185m	>75	<b>4</b> 93	<u> </u>	
	Tin	ppm	ASTM D5185m	>10	0	0	
	Vanadium	ppm	ASTM D5185m		0	0	
	White Metal	scalar	*Visual	NONE	NONE	NONE	
	Yellow Metal	scalar	*Visual	NONE	NONE	NONE	
CONTAMINATION	Silicon	ppm	ASTM D5185m	>20	2	2	
	Potassium	ppm	ASTM D5185m	>20	<1	0	
There is a moderate amount of silt (particulates < 14 microns in size) present in the oil.	Water	1-1-	WC Method	>0.1	NEG	NEG	
	Particles >4µm		ASTM D7647		<b>4</b> 9473	<u></u> 53191	
	Particles >6µm		ASTM D7647		1074	<u>^</u> 2867	
	Particles >14µm		ASTM D7647		46	19	
	Particles >21µm		ASTM D7647		15	4	
	Particles >38μm		ASTM D7647	>10	3	0	
	Particles >71µm		ASTM D7647	>3	1	0	
	Oil Cleanliness		ISO 4406 (c)	>19/17/14	<b>20/17/13</b>	<u>^</u> 23/19/11	
	Silt	scalar	*Visual	NONE	NONE	NONE	
	Debris	scalar	*Visual	NONE	NONE	NONE	
	Sand/Dirt	scalar	*Visual	NONE	NONE	NONE	
	Appearance	scalar	*Visual	NORML	NORML	NORML	
	Odor	scalar	*Visual	NORML	NORML	NORML	
	<b>Emulsified Water</b>	scalar	*Visual	>0.1	NEG	NEG	
LUB CONDITION	0 "		40TM DE40E				
LUID CONDITION	Sodium	ppm	ASTM D5185m	Г	0	2	
he AN level is acceptable for this fluid. The condition of the oil is	Boron	ppm	ASTM D5185m		0	4	
suitable for further service.	Barium	ppm	ASTM D5185m		1	0	
	Molybdenum	ppm	ASTM D5185m	0	<1	<1	
	Manganese	ppm	ASTM D5185m	0E	<1	<1	
	Magnesium	ppm	ASTM D5185m		3	2	
	Calcium	ppm	ASTM D5185m	200	49	51	
	Phosphorus	ppm	ASTM D5185m		272	240	
	Zinc	ppm	ASTM D5185m	370	265	242	
	Sulfur	ppm	ASTM D5185m		4376	3457	
	Acid Number (AN)		ASTM D8045	0.57	0.30	0.219	
	Visc @ 40°C Visc @ 100°C	cSt cSt	ASTM D445 ASTM D445		37.5 6.1	35.9	





Certificate L2367

Laboratory Sample No. Lab Number

: 05750805 **Unique Number** 

: WC0708506 : 10310409

: WearCheck USA - 501 Madison Ave., Cary, NC 27513 Recieved : 26 Jan 2023

Diagnosed : 27 Jan 2023 Diagnostician : Don Baldridge

Test Package : MOB 2 ( Additional Tests: KV100, VI ) To discuss this sample report, contact Customer Service at 1-800-237-1369.

\* - Denotes test methods that are outside of the ISO 17025 scope of accreditation.

**HIAB USA - HAGERSTOWN** 148 WESTERN MARYLAND PKWY

HAGERSTOWN, MD US 21740

Contact: CHUCK WISHARD CHUCK.WISHARD@HIAB.COM T: (240)625-0045

Statements of conformity to specifications are based on the simple acceptance decision rule (JCGM 106:2012)

F: (301)797-7284