



FUEL REPORT

| | |
|----------------|-----------------|
| CORROSION | NORMAL |
| CONTAMINANTS | SEVERE |
| FUEL CONDITION | ABNORMAL |

Machine Id
CHEVROLET 230439309-1 WARD 14 TAHOE





Component
Diesel Fuel

Fluid
{not provided} (--- GAL)

RECOMMENDATION

| Test | UOM | Method | Limit/Abn | Current | History1 | History2 |
|---------------|-----|-------------|-----------|--------------------|----------|----------|
| Sample Number | | Client Info | | WC05884805 | --- | --- |
| Sample Date | | Client Info | | 26 Jun 2023 | --- | --- |
| Machine Age | mls | Client Info | | 0 | --- | --- |
| Sample Status | | | | SEVERE | --- | --- |
| Water | % | ASTM D6304 | <0.05 | 0.052 | --- | --- |
| ppm Water | ppm | ASTM D6304 | <500 | 527.2 | --- | --- |

CORROSION



Certificate L2367

Laboratory : WearCheck USA - 501 Madison Ave., Cary, NC 27513
Sample No. : WC05884805
Lab Number : 05884805
Unique Number : 10535288
Test Package : MOB 2 (Additional Tests: KF, PH, SUGAR)

NATIONAL GENERAL INSURANCE
 PO BOX 1623
 WINSTON SALEM, NC
 US 27102
 Contact: BEN JONES
 BEN.JONES@NGIC.COM

To discuss this sample report, contact Customer Service at 1-800-237-1369.

* - Denotes test methods that are outside of the ISO 17025 scope of accreditation.

Statements of conformity to specifications are based on the simple acceptance decision rule (JCGM 106:2012)

T:
 F: (800)924-0273