WEAR CONTAMINATION FLUID CONDITION

NORMAL NORMAL NORMAL

Aroa

## JOHN CHRISTIANSON [DANIEL/502605]

## **VOLVO PENTA A1078898**

Port Diesel Engine

VOLVO PENTA SAE 15W40 (5 GAL)

RECOMMENDATION	Test	UOM	Method	Limit/Abn	Current	History1	History2
Resample at the next service interval to monitor.	Sample Number		Client Info		VPA059353		
	Sample Date		Client Info		20 Dec 2023		
	Machine Age	hrs	Client Info		248		
	Oil Age	hrs	Client Info		0		
	Filter Age	hrs	Client Info		0		
	Oil Changed		Client Info		Changed		
	Filter Changed		Client Info		Changed		
	Sample Status				NORMAL		
WEAR All component wear rates are normal.	Iron	ppm	ASTM D5185m	>80	19		
	Chromium	ppm	ASTM D5185m		<1		
	Nickel	ppm	ASTM D5185m		2		
	Titanium	ppm	ASTM D5185m		0		
	Silver	ppm	ASTM D5185m		0		
	Aluminum	ppm	ASTM D5185m		4		
	Lead	ppm	ASTM D5185m		3		
	Copper	ppm	ASTM D5185m		10		
	Tin	ppm	ASTM D5185m		<1		
	Vanadium	ppm	ASTM D5185m		0		
	White Metal	scalar	*Visual	NONE	NONE		
	Yellow Metal	scalar	*Visual	NONE	NONE		
CONTAMINATION	Silicon	ppm	ASTM D5185m	>25	8		
There is no indication of any contamination in the oil.	Potassium	ppm	ASTM D5185m	>20	<1		
	Fuel		WC Method	>4.0	<1.0		
	Water		WC Method	>0.1	NEG		
	Glycol		WC Method		NEG		
	Soot %	%	*ASTM D7844		0.2		
	Nitration	Abs/cm	*ASTM D7624	>20	9.3		
	Sulfation	Abs/.1mm	*ASTM D7415	>30	18.7		
	Silt	scalar	*Visual	NONE	NONE		
	Debris	scalar	*Visual	NONE	NONE		
	Sand/Dirt	scalar	*Visual	NONE	NONE		
	Appearance	scalar	*Visual	NORML	NORML		
	Odor	scalar	*Visual	NORML	NORML		
	Emulsified Water	scalar	*Visual	>0.1	NEG		
LUID CONDITION	Sodium	ppm	ASTM D5185m		2		
I LOID CONDITION	Boron	ppm	ASTM D5185m		59		
The BN result indicates that there is suitable alkalinity remaining in the oil. The condition of the oil is acceptable for the time in service.	Barium	ppm	ASTM D5185m		0		
	Molybdenum	ppm	ASTM D5185m		7		
	Manganese	ppm	ASTM D5185m		<1		
	Magnesium	ppm	ASTM D5185m		666		
	Calcium	ppm	ASTM D5185m		1230		
	Phosphorus	ppm	ASTM D5185m		663		
	Zinc	ppm	ASTM D5185m		804		
	Sulfur	ppm	ASTM D5185m		2858		
	Oxidation	Abs/.1mm	*ASTM D7414	>25	14.7		
	Base Number (BN)		ASTM D2896		8.0		
	(511)	9	ASTM D445		13.7		





Certificate L2367

Laboratory Sample No.

: VPA059353 Lab Number : 06044501

: WearCheck USA - 501 Madison Ave., Cary, NC 27513

Received **Tested** Unique Number : 10805109 Diagnosed

Test Package : MOB 1 ( Additional Tests: TBN )

: 27 Dec 2023 : 27 Dec 2023 - Don Baldridge

: 26 Dec 2023

Endor Marine LLC - Coastal Marine - 152124 4300 11th Ave. NW SEATTLE, WA US 98107

Contact: WILLOW YANARELLA service@coastalmarineengine.com

T: (206)784-3703 F: (206)784-8823

To discuss this sample report, contact Customer Service at 1-800-237-1369. \* - Denotes test methods that are outside of the ISO 17025 scope of accreditation.

Statements of conformity to specifications are based on the simple acceptance decision rule (JCGM 106:2012)