



VOLVO

COOLANT REPORT

CORROSION

NORMAL

CONTAMINANTS

NORMAL

COOLANT CONDITION

NORMAL



Machine Id
VOLVO L110H 05631970

Component
Coolant

Fluid
VOLVO COOLANT VCS (YELLOW) (--- GAL)

RECOMMENDATION

No corrective action is recommended at this time. The fluid is suitable for further service.

Test	UOM	Method	Limit/Abn	Current	History1	History2
Sample Number		Client Info		VCP439471	---	---
Sample Date		Client Info		27 Dec 2023	---	---
Machine Age	hrs	Client Info		4896	---	---
Oil Age	hrs	Client Info		0	---	---
Oil Changed		Client Info		Changed	---	---
Sample Status				NORMAL	---	---








CORROSION

Total Dissolved Solids				425.0	---	---
Coolant Appearance		*Visual	Clear	normal	---	---

CONTAMINANTS

There is no indication of any contamination in the coolant.

Specific Gravity		*ASTM D1298		1.069	---	---
pH	Scale 0-14	ASTM D1287		7.23	---	---
Nitrites	ppm	AP-053:2009		NT	---	---
Reserve Alkalinity	Scale 0-20	*ASTM D1121		---	---	---
Percentage Glycol	%	ASTM D3321		51.1	---	---
Freezing Point	°F	ASTM D3321		-38	---	---
Carboxylate				fail	---	---
Coolant Color		*Visual		Yllow	---	---



Certificate L2367

Laboratory : WearCheck USA - 501 Madison Ave., Cary, NC 27513
Sample No. : VCP439471 **Received** : 08 Jan 2024
Lab Number : 06054529 **Diagnosed** : 10 Jan 2024
Unique Number : 10820478 **Diagnostician** : Jonathan Hester
Test Package : COOL - (Additional Tests: COOL)

To discuss this sample report, contact Customer Service at 1-800-237-1369.

* - Denotes test methods that are outside of the ISO 17025 scope of accreditation.

Statements of conformity to specifications are based on the simple acceptance decision rule (JCGM 106:2012)

CITY CARTING
 221 OLD GATE LN
 MILFORD, CT
 US 06460
 Contact: TAVINS BANKS
 tavins@citycart.net
 T: (203)223-3885
 F: