WEAR CONTAMINATION FLUID CONDITION

NORMAL NORMAL



[SUWANNEE CO]
Machine Id
VOLVO L70H 625304

Component Rear Axle

VOLVO WB 102 (GAL)							
RECOMMENDATION	Test	UOM	Method	Limit/Abn	Current	History1	History2
Resample at the next service interval to monitor.	Sample Number		Client Info		VCP418200		
	Sample Date		Client Info		05 Jan 2024		
	Machine Age	hrs	Client Info		510		
	Oil Age	hrs	Client Info		0		
	Filter Age	hrs	Client Info		0		
	Oil Changed		Client Info		Not Changd		
	Filter Changed		Client Info		Not Changd		
	Sample Status				NORMAL		
WEAR	Iron	ppm	ASTM D5185m	>500	114		
All component wear rates are normal.	Chromium	ppm	ASTM D5185m	>20	1		
	Nickel	ppm	ASTM D5185m	>10	<1		
	Titanium	ppm	ASTM D5185m		0		
	Silver	ppm	ASTM D5185m		0		
	Aluminum	ppm	ASTM D5185m	>30	<1		
	Lead	ppm	ASTM D5185m	>50	<1		
	Copper	ppm	ASTM D5185m	>120	12		
	Tin	ppm	ASTM D5185m	>20	1		
	Vanadium	ppm	ASTM D5185m		0		
	White Metal	scalar	*Visual	NONE	NONE		
	Yellow Metal	scalar	*Visual	NONE	NONE		
CONTAMINATION	Silicon	ppm	ASTM D5185m	>50	16		
There is no indication of any contamination in the oil.	Potassium	ppm	ASTM D5185m		<1		
	Water		WC Method	>0.2	NEG		
	Silt	scalar	*Visual	NONE	NONE		
	Debris	scalar	*Visual	NONE	LIGHT		
	Sand/Dirt	scalar	*Visual	NONE	NONE		
	Appearance	scalar	*Visual	NORML	NORML		
	Odor	scalar	*Visual	NORML	NORML		
	Emulsified Water	scalar	*Visual	>0.2	NEG		
FLUID CONDITION	Sodium	ppm	ASTM D5185m		4		
The condition of the oil is acceptable for the time in service.	Boron	ppm	ASTM D5185m		117		
	Barium	ppm	ASTM D5185m		0		
	Molybdenum	ppm	ASTM D5185m		1		
	Manganese	ppm	ASTM D5185m		3		
	Magnesium	ppm	ASTM D5185m		9		
	Calcium	ppm	ASTM D5185m		3689		
	Phosphorus	ppm	ASTM D5185m		1308		
	Zinc	ppm	ASTM D5185m		1563		
	Sulfur	ppm	ASTM D5185m		3758		
	Visc @ 40°C	cSt	ASTM D445	55	41.3		







Certificate L2367

Laboratory Sample No. Lab Number **Unique Number**

: VCP418200 : 06055606 : 10821555 Test Package : MOB 1 To discuss this sample report, contact Customer Service at 1-800-237-1369.

: WearCheck USA - 501 Madison Ave., Cary, NC 27513 Recieved : 09 Jan 2024 : 10 Jan 2024 Diagnosed : Wes Davis Diagnostician

ALTA EQUIPMENT/FLAGLER EQUIPMENT LLC 9601 BOGGY CREEK RD ORLANDO, FL US 32824

Contact: Robert LaPlante robert.laplante@altg.com T: (407)508-9736

* - Denotes test methods that are outside of the ISO 17025 scope of accreditation. Statements of conformity to specifications are based on the simple acceptance decision rule (JCGM 106:2012)

Contact/Location: Robert LaPlante - VOLVO0096

F: (407)659-8720