WEAR CONTAMINATION FLUID CONDITION

NORMAL NORMAL



[634703 MOSAIC]
Machine Id
VOLVO EC480EL 315302

Component Rear Left Final Drive

RECOMMENDATION	Test	UOM	Method	Limit/Abn	Current	History1	History2
Resample at the next service interval to monitor.	Sample Number		Client Info		VCP440779		
Tresample at the flext service interval to monitor.	Sample Date		Client Info		29 Nov 2023		
	Machine Age	hrs	Client Info		516		
	Oil Age	hrs	Client Info		516		
	Filter Age	hrs	Client Info		0		
	Oil Changed		Client Info		Changed		
	Filter Changed		Client Info		Not Changd		
	Sample Status				NORMAL		
VEAR	Iron	ppm	ASTM D5185m	>500	43		
All component wear rates are normal.	Chromium	ppm	ASTM D5185m		0		
	Nickel	ppm	ASTM D5185m		0		
	Titanium	ppm	ASTM D5185m	>10	0		
	Silver	ppm	ASTM D5185m	>2	0		
	Aluminum	ppm	ASTM D5185m		<1		
	Lead	ppm	ASTM D5185m		0		
	Copper	ppm	ASTM D5185m		2		
	Tin	ppm	ASTM D5185m		0		
	Vanadium	ppm	ASTM D5185m		0		
	White Metal	scalar	*Visual	NONE	NONE		
	Yellow Metal	scalar	*Visual	NONE	NONE		
NONT A MUNIA TION							
CONTAMINATION	Silicon	ppm	ASTM D5185m		10		
There is no indication of any contamination in the oil.	Potassium	ppm	ASTM D5185m		<1		
	Water		WC Method	>0.25	NEG		
	Silt	scalar	*Visual	NONE	NONE		
	Debris Sand/Dist	scalar	*Visual	NONE	NONE		
	Sand/Dirt	scalar	*Visual	NONE	NONE NORML		
	Appearance Odor	scalar	*Visual	NORML	NORML		
	Emulsified Water		*Visual	>0.25	NEG		
FLUID CONDITION	Sodium	ppm	ASTM D5185m		<1		
The condition of the oil is acceptable for the time in service.	Boron	ppm	ASTM D5185m		71		
	Barium	ppm	ASTM D5185m		0		
	Molybdenum	ppm	ASTM D5185m		5		
	Manganese	ppm	ASTM D5185m		1		
	Magnesium	ppm	ASTM D5185m		51		
	Calcium	ppm	ASTM D5185m		252		
	Phosphorus	ppm	ASTM D5185m		992		
	Zinc	ppm	ASTM D5185m ASTM D5185m		207 25488		
		ppm					





Certificate L2367

Report Id: VOLVO0093 [WUSCAR] 06063115 (Generated: 01/19/2024 20:36:06) Rev: 1

Laboratory Sample No. Lab Number **Unique Number** 

: VCP440779 : 06063115 : 10834497 Test Package : MOB 1

: WearCheck USA - 501 Madison Ave., Cary, NC 27513 Recieved : 17 Jan 2024 Diagnosed : 18 Jan 2024 : Sean Felton Diagnostician

ALTA EQUIPMENT/FLAGLER CONSTRUCTION EQUIPMENT LLC 8418 PALM RIVER ROAD

TAMPA, FL US 33619 Contact: KENNY HANEY

F: (813)630-2233

khaney@flaglerce.com T: (813)630-0077

To discuss this sample report, contact Customer Service at 1-800-237-1369.

\* - Denotes test methods that are outside of the ISO 17025 scope of accreditation. Statements of conformity to specifications are based on the simple acceptance decision rule (JCGM 106:2012)