WEAR CONTAMINATION FLUID CONDITION

NORMAL NORMAL



[634703 MOSAIC]
Machine Id
VOLVO EC480EL 315302

Right Swing Drive

	_	(G			()		
RECOMMENDATION	Test	UOM	Method	Limit/Abn	Current	History1	History2
Resample at the next service interval to monitor.	Sample Number		Client Info		VCP440616		
	Sample Date		Client Info		29 Nov 2023		
	Machine Age	hrs	Client Info		516		
	Oil Age	hrs	Client Info		516		
	Filter Age	hrs	Client Info		516		
	Oil Changed		Client Info		Changed		
	Filter Changed		Client Info		Not Changd		
	Sample Status				NORMAL		
VEAR	Iron	ppm	ASTM D5185m	>1200	213		
All component wear rates are normal.	Chromium	ppm	ASTM D5185m	>10	3		
	Nickel	ppm	ASTM D5185m	>10	0		
	Titanium	ppm	ASTM D5185m		0		
	Silver	ppm	ASTM D5185m		0		
	Aluminum	ppm	ASTM D5185m	>25	2		
	Lead	ppm	ASTM D5185m	>50	0		
	Copper	ppm	ASTM D5185m	>50	18		
	Tin	ppm	ASTM D5185m	>10	0		
	Vanadium	ppm	ASTM D5185m		0		
	White Metal	scalar	*Visual	NONE	NONE		
	Yellow Metal	scalar	*Visual	NONE	NONE		
CONTAMINATION	Ciliana		ACTM DE10E	100	04		
	Silicon Potassium	ppm	ASTM D5185m ASTM D5185m		21 1		
There is no indication of any contamination in the oil.	Water	ppm	WC Method		NEG		
	Silt	scalar	*Visual	NONE	NONE		
	Debris	scalar	*Visual	NONE	NONE		
	Sand/Dirt	scalar	*Visual	NONE	NONE		
	Appearance	scalar	*Visual	NORML	NORML		
	Odor	scalar	*Visual	NORML	NORML		
	Emulsified Water			>0.25	NEG		
LUID CONDITION	Sodium	ppm	ASTM D5185m		0		
The condition of the oil is acceptable for the time in service.	Boron	ppm	ASTM D5185m	379	0		
	Barium	ppm	ASTM D5185m	0.0	8		
	Molybdenum	ppm	ASTM D5185m		0		
	Manganese	ppm	ASTM D5185m		3		
	Magnesium	ppm	ASTM D5185m	31	0		
	Calcium	ppm	ASTM D5185m		8		
	Phosphorus	ppm	ASTM D5185m		391		
	Zinc	ppm	ASTM D5185m		0		
	Sulfur	ppm	ASTM D5185m	23526	18828		





Certificate L2367

Laboratory Sample No. Lab Number **Unique Number**

: VCP440616 : 06063135 : 10834517 Test Package : MOB 1

To discuss this sample report, contact Customer Service at 1-800-237-1369.

: WearCheck USA - 501 Madison Ave., Cary, NC 27513 Recieved : 17 Jan 2024 Diagnosed : 19 Jan 2024 : Sean Felton Diagnostician

ALTA EQUIPMENT/FLAGLER CONSTRUCTION EQUIPMENT LLC 8418 PALM RIVER ROAD TAMPA, FL US 33619

Contact: KENNY HANEY khaney@flaglerce.com T: (813)630-0077

* - Denotes test methods that are outside of the ISO 17025 scope of accreditation. Statements of conformity to specifications are based on the simple acceptance decision rule (JCGM 106:2012)

F: (813)630-2233