WEAR CONTAMINATION **FLUID CONDITION**

NORMAL NORMAL NORMAL



Machine Id LIFRHERR I H30M 1253-123497

LIEBHERR LH30M 1253-12 Component Front Left Wheel Hub Fluid GEAR OIL SAE 80W90 (GAL							
RECOMMENDATION	Test	UOM	Method	Limit/Abn	Current	History1	History2
Resample at the next service interval to monitor. Please specify the brand, type, and viscosity of the oil on your next sample.	Sample Number		Client Info		LH0272903	LH0212311	
	Sample Date		Client Info		11 Jan 2024	30 Dec 2021	
	Machine Age	hrs	Client Info		4554	981	
	Oil Age	hrs	Client Info		0	0	
	Filter Age	hrs	Client Info		0	0	
	Oil Changed		Client Info		Changed	Changed	
	Filter Changed		Client Info		N/A	None	
	Sample Status				NORMAL	NORMAL	
WEAR All component wear rates are normal.	Iron	ppm	ASTM D5185m	>450	34	58	
	Chromium	ppm	ASTM D5185m	>4	<1	<1	
	Nickel	ppm	ASTM D5185m	>2	0	0	
	Titanium	ppm	ASTM D5185m		0	<1	
	Silver	ppm	ASTM D5185m		0	<1	
	Aluminum	ppm	ASTM D5185m	>15	2	0	
	Lead	ppm	ASTM D5185m	>4	0	<1	
	Copper	ppm	ASTM D5185m	>75	5	16	
	Tin	ppm	ASTM D5185m		0	<1	
	Vanadium	ppm	ASTM D5185m		0	0	
	White Metal	scalar	*Visual	NONE	NONE	MODER	
	Yellow Metal	scalar	*Visual	NONE	NONE	NONE	
CONTAMINATION	Silicon	ppm	ASTM D5185m	>60	2	6	
There is no indication of any contamination in the oil.	Potassium	ppm	ASTM D5185m		<1	0	
	Water		WC Method		NEG	NEG	
	Silt	scalar	*Visual	NONE	NONE	VLITE	
	Debris	scalar	*Visual	NONE	NONE	NONE	
	Sand/Dirt	scalar	*Visual	NONE	NONE	NONE	
	Appearance	scalar	*Visual	NORML	NORML	NORML	
	Odor	scalar	*Visual	NORML	NORML	NORML	
	Emulsified Water	scalar	*Visual	>0.2	NEG	NEG	
FLUID CONDITION	Sodium	ppm	ASTM D5185m		<1	6	
The condition of the oil is acceptable for the time in service.	Boron	ppm	ASTM D5185m		1	69	
	Barium	ppm	ASTM D5185m		3	0	
	Molybdenum	ppm	ASTM D5185m	12	0	<1	
	Manganese	ppm	ASTM D5185m		0	1	
	Magnesium	ppm	ASTM D5185m		1	2	
	Calcium	ppm	ASTM D5185m		98	495	
	Phosphorus	ppm	ASTM D5185m		320	542	
	Zinc	ppm	ASTM D5185m	125	3	293	

Sulfur

Visc @ 40°C

ASTM D5185m 22500


ASTM D445 143


16526


122


19706

107











Laboratory Sample No. Lab Number

: LH0272903 : 06063174 Unique Number : 10834556 Test Package : CONST

: WearCheck USA - 501 Madison Ave., Cary, NC 27513 Recieved : 17 Jan 2024 Diagnosed : 18 Jan 2024 Diagnostician : Wes Davis

SPARTAN RECYCLING

3071 HOWARD ST SPARTANBURG, SC US 29303

Contact: SERVICE MANAGER

To discuss this sample report, contact Customer Service at 1-800-237-1369.

* - Denotes test methods that are outside of the ISO 17025 scope of accreditation.

Statements of conformity to specifications are based on the simple acceptance decision rule (JCGM 106:2012)

T:

F: