



OIL ANALYSIS REPORT

WEAR	---
CONTAMINATION	---
FLUID CONDITION	---



Area  
**[ro#146831]**  
Machine Id  
**JOHN DEERE 310E 1DW310EXANF714535**  
Component  
**Diesel Engine**  
Fluid  
**JOHN DEERE ENGINE OIL PLUS 50 II 15W40 (11 GAL)**

*Sample is currently in the laboratory*

**Sample is currently in the laboratory**



Certificate L2367

**Laboratory** : WearCheck USA - 501 Madison Ave., Cary, NC 27513  
**Sample No.** : LEC0046782 **Recieved** : 18 Jan 2024  
**Lab Number** : 06064014 **Diagnosed** :  
**Unique Number** : 10835396 **Diagnostician** :  
**Test Package** : CONST ( Additional Tests: TBN )

To discuss this sample report, contact Customer Service at 1-800-237-1369.

\* - Denotes test methods that are outside of the ISO 17025 scope of accreditation.

Statements of conformity to specifications are based on the simple acceptance decision rule (JCGM 106:2012)

**LESLIE EQUIPMENT COMPANY**  
105 TENNIS CENTER DR.  
MARIETTA, OH  
US 45750-9765  
Contact: LEANNE KENDALL  
KendalLeanne@lec1.com  
T:  
F: (740)373-5570