
**WEAR CONTAMINATION FLUID CONDITION**  **ABNORMAL NORMAL NORMAL** 

Area [659478]

**VOLVO A40G 315157** 

Wet Disc Brake

	RANSAXLE				/		
RECOMMENDATION	Test	UOM	Method	Limit/Abn	Current	History1	History2
No corrective action is recommended at this time. Resample at the next service interval to monitor.	Sample Number		Client Info		VCP437459		
	Sample Date		Client Info		11 Jan 2024		
	Machine Age	hrs	Client Info		2059		
	Oil Age	hrs	Client Info		0		
	Filter Age	hrs	Client Info		0		
	Oil Changed		Client Info		Not Changd		
	Filter Changed		Client Info		Changed		
	Sample Status				ABNORMAL		
VEAR	Iron	ppm	ASTM D5185m	>20	20		
The copper level is abnormal.	Chromium	ppm	ASTM D5185m	>10	<1		
	Nickel	ppm	ASTM D5185m	>10	6		
	Titanium	ppm	ASTM D5185m		0		
	Silver	ppm	ASTM D5185m		0		
	Aluminum	ppm	ASTM D5185m	>10	2		
	Lead	ppm	ASTM D5185m	>10	0		
	Copper	ppm	ASTM D5185m	>75	<u> </u>		
	Tin	ppm	ASTM D5185m	>10	0		
	Vanadium	ppm	ASTM D5185m		0		
	White Metal	scalar	*Visual	NONE	LIGHT		
	Yellow Metal	scalar	*Visual	NONE	NONE		
CONTAMINATION	Silicon	nnm	ASTM D5185m	>20	21		
	Potassium	ppm	ASTM D5185m		2		
There is no indication of any contamination in the oil.	Water	ppiii	WC Method	>0.1	NEG		
	Silt	scalar	*Visual	NONE	NONE		
	Debris	scalar	*Visual	NONE	NONE		
	Sand/Dirt	scalar	*Visual	NONE	NONE		
	Appearance	scalar	*Visual	NORML	NORML		
	Odor	scalar	*Visual	NORML	NORML		
	Emulsified Water	scalar	*Visual	>0.1	NEG		
I LUD CONDITION							
FLUID CONDITION	Sodium	ppm	ASTM D5185m		6		
The condition of the oil is acceptable for the time in service.	Boron	ppm	ASTM D5185m		131		
	Barium	ppm	ASTM D5185m		3		
	Molybdenum	ppm	ASTM D5185m		0		
	Magnesium	ppm	ASTM D5185m		<1		
	Magnesium	ppm	ASTM D5185m		7		
	Calcium	ppm	ASTM D5185m		3622 1264		
	Phosphorus Zinc	ppm	ASTM D5185m ASTM D5185m		1599		
	Sulfur	ppm	ASTM D5185m		4953		
	Sullul	ppm	AO INI DO IOSIII		4300		





Certificate L2367

Laboratory Sample No. Lab Number **Unique Number** 

: VCP437459 : 06064615 : 10835997 Test Package : MOB 1

: WearCheck USA - 501 Madison Ave., Cary, NC 27513 : 18 Jan 2024 Recieved

Diagnosed : 21 Jan 2024 Diagnostician : Don Baldridge JON M HALL COMPANY

1920 BOOTHE CIRCLE SUITE 110 LONGWOOD, FL US 32750

Contact: SERVICE MANAGER

To discuss this sample report, contact Customer Service at 1-800-237-1369.

\* - Denotes test methods that are outside of the ISO 17025 scope of accreditation. Statements of conformity to specifications are based on the simple acceptance decision rule (JCGM 106:2012) T: (407)215-0410 F:

Contact/Location: SERVICE MANAGER - JONLON