

CORROSION CONTAMINANTS COOLANT CONDITION

NORMAL NORMAL NORMAL





Area [W63109]

JOHN DEERE 210G 1FF210GXHJF526691

Component Coolant

(not provided) (GAL)							
RECOMMENDATION	Test	UOM	Method	Limit/Abn	Current	History1	History2
The fluid is suitable for further service. (Customer Sample Comment: W63109 $)$	Sample Number		Client Info		JR0198600	JR0178702	JR0161968
	Sample Date		Client Info		16 Jan 2024	17 Aug 2023	28 Apr 2023
	Machine Age	hrs	Client Info		3539	2989	2639
	Oil Age	hrs	Client Info		2784	2718	0
	Oil Changed		Client Info		Not Changd	Not Changd	Not Changd
	Sample Status				NORMAL	NORMAL	NORMAL
CORROSION	Total Dissolved Solids				422.5	404.5	396.5
	Coolant Appearance		*Visual	Clear	normal	normal	hazy
CONTAMINANTS There is no indication of any contamination in the coolant.	Specific Gravity		*ASTM D1298		1.072	1.067	1.068
	рН	Scale 0-14	ASTM D1287		7.28	8.40	7.13
	Nitrites	ppm	AP-053:2009		0	0	0
	Reserve Alkalinity	Scale 0-20	*ASTM D1121				
	Percentage Glycol	%	ASTM D3321		53.8	50.0	50.8
	Freezing Point	°F	ASTM D3321		-43	-35	-35
	Carboxylate				n/a	n/a	n/a
	Coolant Color		*Visual		Yllow	Yllow	Yllow







Certificate L2367

Laboratory Sample No. Lab Number **Unique Number**

: WearCheck USA - 501 Madison Ave., Cary, NC 27513

: JR0198600 : 06064666 : 10836048

Recieved : 18 Jan 2024 Diagnosed

: 25 Jan 2024 Diagnostician : Doug Bogart

Test Package : COOL- (Additional Tests: COOL, PQ)

To discuss this sample report, contact Customer Service at 1-800-237-1369.

* - Denotes test methods that are outside of the ISO 17025 scope of accreditation. Statements of conformity to specifications are based on the simple acceptance decision rule (JCGM 106:2012)

JRE - CHARLOTTE 9550 STATESVILLE ROAD

CHARLOTTE, NC US 28269

Contact: CHARLOTTE SHOP myoung@jamesriverequipment.com

T: (704)597-0211

F: (704)596-6198