WEAR CONTAMINATION FLUID CONDITION

NORMAL NORMAL NORMAL

Machine Io

OSHKOSH MIXER 4410

Component Diesel Engine

RECOMMENDATION	Test	UOM	Method	Limit/Abn	Current	History1	History2
	Sample Number		Client Info		WC0893868		
Resample at the next service interval to monitor.	Sample Date		Client Info		19 Jan 2024		
	Machine Age	mls	Client Info		32079		
	Oil Age	mls	Client Info		0		
	Filter Age	mls	Client Info		0		
	Oil Changed		Client Info		Changed		
	Filter Changed		Client Info		Changed		
	Sample Status				NORMAL		
VEAR	Iron	nnm	ASTM D5185m	> 100	2		
VLAN	Chromium	ppm	ASTM D5185m		<1		
Metal levels are typical for a new component breaking in.	Nickel	ppm	ASTM D5185m		0		
	Titanium	ppm	ASTM D5185m	>4			
	Silver	ppm	ASTM D5185m	. 0	0		
		ppm			0		
	Aluminum	ppm	ASTM D5185m		<1		
	Lead	ppm	ASTM D5185m	-	0		
	Copper	ppm	ASTM D5185m		0		
	Tin	ppm	ASTM D5185m	>15	0		
	Vanadium	ppm	ASTM D5185m	NONE	0		
	White Metal	scalar	*Visual	NONE	NONE		
<u></u>	Yellow Metal	scalar	*Visual	NONE	NONE		
CONTAMINATION	Silicon	ppm	ASTM D5185m	>25	3		
There is no indication of any contamination in the oil.	Potassium	ppm	ASTM D5185m	>20	0		
	Fuel		WC Method	>5	<1.0		
	Water		WC Method	>0.2	NEG		
	Glycol		WC Method		NEG		
	Soot %	%	*ASTM D7844	>3	0.2		
	Nitration	Abs/cm	*ASTM D7624	>20	6.2		
	Sulfation	Abs/.1mm	*ASTM D7415	>30	18.1		
	Silt	scalar	*Visual	NONE	NONE		
	Debris	scalar	*Visual	NONE	NONE		
	Sand/Dirt	scalar	*Visual	NONE	NONE		
	Appearance	scalar	*Visual	NORML	NORML		
	Odor	scalar	*Visual	NORML	NORML		
	Emulsified Water	scalar	*Visual	>0.2	NEG		
LUID CONDITION	Sodium	nnm	ASTM D5185m	>118	2		
	Boron	ppm	ASTM D5185m	/110	4		
The BN result indicates that there is suitable alkalinity remaining in the oil. The condition of the oil is suitable for further service.	Barium	ppm	ASTM D5185m		0		
	Molybdenum	ppm	ASTM D5185m		57		
	Manganese	ppm	ASTM D5185m		<1		
	Magnesium	ppm	ASTM D5185m		925		
	Calcium	ppm	ASTM D5185m		1046		
	Phosphorus	ppm	ASTM D5185m		1051		
	Zinc		ASTM D5185m		1229		
	Sulfur	ppm	ASTM D5185m				
	Oxidation	ppm Abc/ 1mm	*ASTM D5185m	> 2F	2950		
	Base Number (BN)	Abs/.1mm		>20	14.0		
	pase number (BIV)	IIIQ NUM/Q	49 LIVI D5896		8.8		







Laboratory Sample No.

: WC0893868 Lab Number : 06085929 Unique Number : 10873374

Test Package : MOB 1 (Additional Tests: TBN)

: WearCheck USA - 501 Madison Ave., Cary, NC 27513 Received : 12 Feb 2024 **Tested** : 13 Feb 2024 Diagnosed

: 13 Feb 2024 - Wes Davis

CONCRETE SERVICE CO - FAY BLOCK 161 BUILDERS BLVD

FAYETTEVILLE, NC US 28301 Contact: Service Manager

To discuss this sample report, contact Customer Service at 1-800-237-1369.

* - Denotes test methods that are outside of the ISO 17025 scope of accreditation.

Statements of conformity to specifications are based on the simple acceptance decision rule (JCGM 106:2012)

T:

F: