WEAR CONTAMINATION FLUID CONDITION

NORMAL NORMAL

[3591 BULK EXPRESS]
Machine Id
VOLVO L150H 6957

Component Front Axle

TDH FLUID SAE 75W80 (
RECOMMENDATION	Test	UOM	Method	Limit/Abn	Current	History1	History2
Resample at the next service interval to monitor.	Sample Number		Client Info		VCP441778		
	Sample Date		Client Info		07 Feb 2024		
	Machine Age	hrs	Client Info		7032		
	Oil Age	hrs	Client Info		0		
	Filter Age	hrs	Client Info		0		
	Oil Changed		Client Info		Changed		
	Filter Changed		Client Info		Not Changd		
	Sample Status				NORMAL		
WEAR	Iron	ppm	ASTM D5185m	>500	25		
All component wear rates are normal.	Chromium	ppm	ASTM D5185m	>20	<1		
	Nickel	ppm	ASTM D5185m	>10	0		
	Titanium	ppm	ASTM D5185m		0		
	Silver	ppm	ASTM D5185m		0		
	Aluminum	ppm	ASTM D5185m	>30	1		
	Lead	ppm	ASTM D5185m	>50	0		
	Copper	ppm	ASTM D5185m	>120	0		
	Tin	ppm	ASTM D5185m	>20	0		
	Vanadium	ppm	ASTM D5185m		0		
	White Metal	scalar	*Visual	NONE	NONE		
	Yellow Metal	scalar	*Visual	NONE	NONE		
CONTAMINATION	Silicon	ppm	ASTM D5185m	>50	13		
There is no indication of any contamination in the oil.	Potassium	ppm	ASTM D5185m		0		
	Water	le le	WC Method		NEG		
	Silt	scalar	*Visual	NONE	NONE		
	Debris	scalar	*Visual	NONE	NONE		
	Sand/Dirt	scalar	*Visual	NONE	NONE		
	Appearance	scalar	*Visual	NORML	NORML		
	Odor	scalar	*Visual	NORML	NORML		
	Emulsified Water	scalar	*Visual	>0.2	NEG		
FLUID CONDITION	Sodium	ppm	ASTM D5185m		3		
The condition of the oil is acceptable for the time in service.	Boron	ppm	ASTM D5185m	10	137		
	Barium	ppm	ASTM D5185m		0		
	Molybdenum	ppm	ASTM D5185m		2		
	Manganese	ppm	ASTM D5185m		1		
	Magnesium	ppm	ASTM D5185m	100	29		
	Calcium	ppm	ASTM D5185m	3500	3579		
	Phosphorus	ppm	ASTM D5185m	1150	1246		
	Zinc	ppm	ASTM D5185m	1150	1464		
	Sulfur	ppm	ASTM D5185m	5000	4474		
	Visc @ 40°C	cSt	ASTM D445	48	42.5		





Certificate L2367

Laboratory Sample No.

Lab Number : 06086399 Unique Number : 10873844 Test Package : MOB 1

: WearCheck USA - 501 Madison Ave., Cary, NC 27513 : VCP441778 Received : 12 Feb 2024 **Tested**

: 13 Feb 2024 : 13 Feb 2024 - Don Baldridge Diagnosed

ALTA EQUIPMENT/FLAGLER EQUIPMENT LLC 9601 BOGGY CREEK RD

ORLANDO, FL US 32824

Contact: Robert LaPlante robert.laplante@altg.com T: (407)508-9736

To discuss this sample report, contact Customer Service at 1-800-237-1369. * - Denotes test methods that are outside of the ISO 17025 scope of accreditation.

Statements of conformity to specifications are based on the simple acceptance decision rule (JCGM 106:2012)

Report Id: VOLVO0096 [WUSCAR] 06086399 (Generated: 02/13/2024 18:51:52) Rev: 1

Contact/Location: Robert LaPlante - VOLVO0096

F: (407)659-8720