
CORROSION CONTAMINANTS COOLANT CONDITION **NORMAL NORMAL NORMAL**


JOHN DEERE 5780 1H05780SEKT806479

Component Coolant

Inot provided (--GAL)

{not provided} (GAL)							
RECOMMENDATION	Test	UOM	Method	Limit/Abn	Current	History1	History2
The fluid is suitable for further service.	Sample Number		Client Info		JR0201776		
	Sample Date		Client Info		13 Feb 2024		
	Machine Age	hrs	Client Info		0		
	Oil Age	hrs	Client Info		0		
	Oil Changed		Client Info		N/A		
	Sample Status				NORMAL		
CORROSION	Total Dissolved Solids				333.5		
	Coolant Appearance		*Visual	Clear	normal		
CONTAMINANTS	Specific Gravity		*ASTM D1298		1.068		
There is no indication of any contamination in the coolant.	рН	Scale 0-14	ASTM D1287		7.76		
	Nitrites	ppm	AP-053:2009		NT		
	Reserve Alkalinity	Scale 0-20	*ASTM D1121				
	Percentage Glycol	%	ASTM D3321		50.4		
	Freezing Point	°F	ASTM D3321		-35		
	Carboxylate				n/a		
	Coolant Color		*Visual		Yllow		









Laboratory

Sample No.

Lab Number : 06087894 Unique Number: 10875339

: JR0201776

: WearCheck USA - 501 Madison Ave., Cary, NC 27513 Received **Tested**

: 13 Feb 2024 : 15 Feb 2024 Diagnosed

: 15 Feb 2024 - Jonathan Hester Test Package : COOL- (Additional Tests: COOL, PQ)

JRE - WAKEFIELD 10489 GENERAL MAHONE HWY WAKEFIELD, VA

US 23888 Contact: BILL ACKER

backer@jamesriverequipment.com T: (757)899-3232

To discuss this sample report, contact Customer Service at 1-800-237-1369. * - Denotes test methods that are outside of the ISO 17025 scope of accreditation. Statements of conformity to specifications are based on the simple acceptance decision rule (JCGM 106:2012)

F: (757)899-6464

Contact/Location: BILL ACKER - JAMWAK