**WEAR** CONTAMINATION **FLUID CONDITION** 


**NORMAL NORMAL NORMAL** 





Area (69J4UN) 929096-205270


Component Transmission (Auto)

	HD Synthetic (						
RECOMMENDATION	Test	UOM	Method	Limit/Abn	Current	History1	History2
Resample at the next service interval to monitor.	Sample Number		Client Info		GFL0108102		
	Sample Date		Client Info		02 Feb 2024		
	Machine Age	hrs	Client Info		4310		
	Oil Age	hrs	Client Info		0		
	Filter Age	hrs	Client Info		0		
	Oil Changed		Client Info		Not Changd		
	Filter Changed		Client Info		Changed		
	Sample Status				NORMAL		
VEAR	Iron	ppm	ASTM D5185m	>220	62		
All component wear rates are normal.	Chromium	ppm	ASTM D5185m	>2	0		
	Nickel	ppm	ASTM D5185m	>5	<1		
	Titanium	ppm	ASTM D5185m		0		
	Silver	ppm	ASTM D5185m	>5	0		
	Aluminum	ppm	ASTM D5185m	>75	16		
	Lead	ppm	ASTM D5185m	>95	5		
	Copper	ppm	ASTM D5185m	>60	33		
	Tin	ppm	ASTM D5185m	>10	2		
	Vanadium	ppm	ASTM D5185m		0		
	White Metal	scalar	*Visual	NONE	NONE		
	Yellow Metal	scalar	*Visual	NONE	NONE		
CONTAMINATION	Silicon	ppm	ASTM D5185m	>25	4		
There is no indication of any contamination in the fluid.	Potassium	ppm	ASTM D5185m		2		
	Water	le le	WC Method		NEG		
	Silt	scalar	*Visual	NONE	NONE		
	Debris	scalar	*Visual	NONE	NONE		
	Sand/Dirt	scalar	*Visual	NONE	NONE		
	Appearance	scalar	*Visual	NORML	NORML		
	Odor	scalar	*Visual	NORML	NORML		
	Emulsified Water	scalar	*Visual	>0.1	NEG		
LUID CONDITION	Sodium	ppm	ASTM D5185m		11		
	Boron	ppm	ASTM D5185m		259		
The condition of the fluid is acceptable for the time in service.	Barium	ppm	ASTM D5185m		0		
	Molybdenum	ppm	ASTM D5185m		0		
	Manganese	ppm	ASTM D5185m		<1		
	Magnesium	ppm	ASTM D5185m		0		
	Calcium	ppm	ASTM D5185m		206		
	Phosphorus	ppm	ASTM D5185m		588		
	Zinc	ppm	ASTM D5185m		0		
	Sulfur	ppm	ASTM D5185m		2008		











Laboratory Sample No.

: GFL0108102 Lab Number : 06088443 Unique Number: 10875888 Test Package : FLEET

: WearCheck USA - 501 Madison Ave., Cary, NC 27513 Received : 13 Feb 2024 **Tested** 

: 14 Feb 2024 Diagnosed : 14 Feb 2024 - Wes Davis

GFL Environmental - 823 - Central Missouri Hauling 24461 Oak Grove Lane Sedalia, MO

US 65301 Contact: Terry Randolph trandolph@gflenv.com T: (660)631-2116

To discuss this sample report, contact Customer Service at 1-800-237-1369. \* - Denotes test methods that are outside of the ISO 17025 scope of accreditation.

Statements of conformity to specifications are based on the simple acceptance decision rule (JCGM 106:2012)

Report Id: GFL823 [WUSCAR] 06088443 (Generated: 02/15/2024 11:25:50) Rev: 1