

WEAR CONTAMINATION FLUID CONDITION


NORMAL NORMAL

Area

SUSAN EIDE [DILLON] Machine Id VOLVO PENTA 3940028072

Port IPS

RECOMMENDATION	Test	UOM	Method	Limit/Abn	Current	History1	History2
Resample at the next service interval to monitor.	Sample Number		Client Info		VPA060408	VPA045529	
	Sample Date		Client Info		20 Feb 2024	07 Mar 2023	
	Machine Age	hrs	Client Info		913	0	
	Oil Age	hrs	Client Info		0	0	
	Filter Age	hrs	Client Info		0	0	
	Oil Changed		Client Info		Changed	Changed	
	Filter Changed		Client Info		Changed	Changed	
	Sample Status				NORMAL	NORMAL	
WEAR	PQ		ASTM D8184		22	23	
All component wear rates are normal.	Iron	ppm	ASTM D5185m	>200	54	71	
	Chromium	ppm	ASTM D5185m	>10	<1	1	
	Nickel	ppm	ASTM D5185m	>10	<1	<1	
	Titanium	ppm	ASTM D5185m		0	<1	
	Silver	ppm	ASTM D5185m		0	0	
	Aluminum	ppm	ASTM D5185m		<1	1	
	Lead	ppm	ASTM D5185m		0	0	
	Copper	ppm	ASTM D5185m		4	6	
	Tin	ppm	ASTM D5185m		<1	<1	
	Vanadium	ppm	ASTM D5185m		0	<1	
	White Metal	scalar	*Visual	NONE	NONE	NONE	
	Yellow Metal	scalar	*Visual	NONE	NONE	NONE	
CONTAMINATION There is no indication of any contamination in the oil.	Silicon	ppm	ASTM D5185m		9	12	
	Potassium	ppm	ASTM D5185m	>20	0	3	
	Water		WC Method	>0.2	NEG	NEG	
	Silt	scalar	*Visual	NONE	NONE	NONE	
	Debris	scalar	*Visual	NONE	NONE	LIGHT	
	Sand/Dirt	scalar	*Visual	NONE	NONE	NONE	
	Appearance	scalar	*Visual	NORML	NORML	NORML	
	Odor	scalar	*Visual	NORML	NORML	NORML	
	Emulsified Water	scalar	*Visual	>0.2	NEG	NEG	
FLUID CONDITION	Sodium	ppm	ASTM D5185m		<1	2	
The condition of the oil is acceptable for the time in service.	Boron	ppm	ASTM D5185m		278	300	
	Barium	ppm	ASTM D5185m		0	0	
	Molybdenum	ppm	ASTM D5185m		0	2	
	Manganese	ppm	ASTM D5185m		1	5	
	Magnesium	ppm	ASTM D5185m		0	102	
	Calcium	ppm	ASTM D5185m		7	31	
	Phosphorus	ppm	ASTM D5185m		1245	1247	
	Zinc	ppm	ASTM D5185m		0	0	
	Sulfur	ppm	ASTM D5185m		22099	25056	
	Visc @ 40°C	cSt	ASTM D445		106	105	





Certificate L2367

Laboratory Sample No.

Lab Number : 06097281

: VPA060408

: WearCheck USA - 501 Madison Ave., Cary, NC 27513 Received : 22 Feb 2024 **Tested**

Unique Number : 10890134 Diagnosed

: 23 Feb 2024 : 24 Feb 2024 - Don Baldridge

Test Package: MOB 1 (Additional Tests: PQ) To discuss this sample report, contact Customer Service at 1-800-237-1369.

* - Denotes test methods that are outside of the ISO 17025 scope of accreditation. Statements of conformity to specifications are based on the simple acceptance decision rule (JCGM 106:2012)

Endor Marine LLC - Coastal Marine - 152124

4300 11th Ave. NW SEATTLE, WA US 98107

T: (206)784-3703

Contact: WILLOW YANARELLA service@coastalmarineengine.com

F: (206)784-8823 Contact/Location: WILLOW YANARELLA - VP794951