WEAR CONTAMINATION FLUID CONDITION

NORMAL NORMAL

Machine Id

RO 91035

Component Rear Differential

MOBIL 75W90 (8 QTS)							
RECOMMENDATION	Test	UOM	Method	Limit/Abn	Current	History1	History2
Resample at the next service interval to monitor.	Sample Number		Client Info		WC0824093		
	Sample Date		Client Info		12 Feb 2024		
	Machine Age	mls	Client Info		43973		
	Oil Age	mls	Client Info		0		
	Filter Age	mls	Client Info		0		
	Oil Changed		Client Info		N/A		
	Filter Changed		Client Info		N/A		
	Sample Status				NORMAL		
WEAR	Iron	ppm	ASTM D5185m	>500	286		
All component wear rates are normal.	Chromium	ppm	ASTM D5185m	>10	2		
	Nickel	ppm	ASTM D5185m	>10	<1		
	Titanium	ppm	ASTM D5185m		0		
	Silver	ppm	ASTM D5185m		0		
	Aluminum	ppm	ASTM D5185m	>25	1		
	Lead	ppm	ASTM D5185m	>25	0		
	Copper	ppm	ASTM D5185m	>100	2		
	Tin	ppm	ASTM D5185m	>10	<1		
	Vanadium	ppm	ASTM D5185m		0		
	White Metal	scalar	*Visual	NONE	NONE		
	Yellow Metal	scalar	*Visual	NONE	NONE		
CONTAMINATION	Silicon	ppm	ASTM D5185m	>75	35		
There is no indication of any contamination in the oil.	Potassium	ppm	ASTM D5185m	>20	8		
	Water		WC Method	>.2	NEG		
	Silt	scalar	*Visual	NONE	NONE		
	Debris	scalar	*Visual	NONE	NONE		
	Sand/Dirt	scalar	*Visual	NONE	NONE		
	Appearance	scalar	*Visual	NORML	NORML		
	Odor	scalar	*Visual	NORML	NORML		
	Emulsified Water	scalar	*Visual	>.2	NEG		
FLUID CONDITION	Sodium	ppm	ASTM D5185m		13		
The condition of the oil is acceptable for the time in service.	Boron	ppm	ASTM D5185m		270		
	Barium	ppm	ASTM D5185m		6		
	Molybdenum	ppm	ASTM D5185m		<1		
	Manganese	ppm	ASTM D5185m		16		
	Magnesium	ppm	ASTM D5185m		<1		
	Calcium	ppm	ASTM D5185m		11		
	Phosphorus	ppm	ASTM D5185m		1575		
	Zinc	ppm	ASTM D5185m		23		
	Sulfur	ppm	ASTM D5185m		25993		
	Visc @ 40°C	cSt	ASTM D445		120		





Certificate L2367

Laboratory Sample No.

: WC0824093 Lab Number : 06098032 Unique Number: 10896262 Test Package : MOB 1

: WearCheck USA - 501 Madison Ave., Cary, NC 27513 Received : 22 Feb 2024 **Tested** : 23 Feb 2024

: 23 Feb 2024 - Wes Davis Diagnosed

ATEL BUS & TRUCK 12120 CONWAY RD BELTSVILLE, MD US 20705

Contact: OSCAR ROMERO oromero@atelbus.com

To discuss this sample report, contact Customer Service at 1-800-237-1369.

* - Denotes test methods that are outside of the ISO 17025 scope of accreditation.

Statements of conformity to specifications are based on the simple acceptance decision rule (JCGM 106:2012)

T:

F: