

WEAR	
CONTAMINATION	
FLUID CONDITION	

Machine Id

JOHN DEERE 1FF350GXVKF814250

Component Diesel Engine

JOHN DEERE ENGINE OIL PLUS 50 II 15W40 (--- GAL)

Sample is currently in the laboratory

Sample is currently in the laboratory



Laboratory

Sample No. : JR0195854 Lab Number : 06098903 Unique Number : 10897133

: WearCheck USA - 501 Madison Ave., Cary, NC 27513 Received Tested

Diagnosed

: 23 Feb 2024

TOTAL DEVELOPMENT SOLUTIONS LLC 7805 PROGRESS CT GAINESVILLE, VA US 20155 Contact: JOE SEALE

Test Package : CONST (Additional Tests: FuelDilution, PercentFuel, TBN) To discuss this sample report, contact Customer Service at 1-800-237-1369.

* - Denotes test methods that are outside of the ISO 17025 scope of accreditation. Statements of conformity to specifications are based on the simple acceptance decision rule (JCGM 106:2012)

T: (571)220-7763 F: (703)753-4586