

Machine Id JOHN DEERE 524L 1DW524LTPMF710019 Component Front Axle Fluid {not provided} (--- GAL)

RECOMMENDATION	Test	UOM	Method	Limit/Abn	Current	History1	History2
Resample at the next service interval to monitor.	Sample Number		Client Info		JR0204343		
	Sample Date		Client Info		21 Feb 2024		
	Machine Age	hrs	Client Info		7035		
	Oil Age	hrs	Client Info		7035		
	Filter Age	hrs	Client Info		0		
	Oil Changed		Client Info		Not Changd		
	Filter Changed		Client Info		N/A		
	Sample Status				NORMAL		
WEAR	PQ		ASTM D8184		142		
	Iron	ppm	ASTM D5185m	>750	673		
All component wear rates are normal.	Chromium		ASTM D5185m		3		
	Nickel	ppm ppm	ASTM D5185m		3		
	Titanium	ppm	ASTM D5185m	210	0		
	Silver	ppm	ASTM D5185m		0		
	Aluminum	ppm	ASTM D5185m	>21	1		
	Lead	ppm	ASTM D5185m		10		
	Copper	ppm	ASTM D5185m		38		
	Tin	ppm	ASTM D5185m		1		
	Vanadium	ppm	ASTM D5185m		0		
	White Metal	scalar	*Visual	NONE	NONE		
	Yellow Metal	scalar	*Visual	NONE	NONE		
CONTAMINATION There is no indication of any contamination in the oil.	Silicon	ppm	ASTM D5185m		27		
	Potassium	ppm	ASTM D5185m		8		
	Water		WC Method		NEG		
	Silt	scalar	*Visual	NONE	NONE		
	Debris	scalar	*Visual	NONE	NONE		
	Sand/Dirt	scalar	*Visual	NONE	NONE		
	Appearance	scalar	*Visual	NORML	NORML		
	Odor	scalar	*Visual	NORML	NORML		
	Emulsified Water	scalar	*Visual	>0.1	NEG		
FLUID CONDITION	Sodium	ppm	ASTM D5185m	>51	4		
The condition of the oil is acceptable for the time in service.	Boron	ppm	ASTM D5185m		6		
	Barium	ppm	ASTM D5185m		0		
	Molybdenum	ppm	ASTM D5185m		1		
	Manganese	ppm	ASTM D5185m		12		
	Magnesium	ppm	ASTM D5185m		103		
	Calcium	ppm	ASTM D5185m		3689		
	Phosphorus	ppm	ASTM D5185m		1128		
	Zinc	ppm	ASTM D5185m		1339		
	Sulfur	ppm	ASTM D5185m		4535		
						1	


Visc @ 40°C


cSt


ASTM D445

Submitted By: Ray Benson

53.4







Submitted By: Ray Benson

Page 2 of 2

Feb21/24