
WEAR CONTAMINATION FLUID CONDITION **NORMAL NORMAL NORMAL**

Area [47235]

VOLVO A40G 353015

Component Rear Axle

	90 (GAL)						
RECOMMENDATION	Test	UOM	Method	Limit/Abn	Current	History1	History2
Resample at the next service interval to monitor.	Sample Number		Client Info		VCP417723	VCP389692	
	Sample Date		Client Info		22 Feb 2024	30 Nov 2022	
	Machine Age	hrs	Client Info		2828	1091	
	Oil Age	hrs	Client Info		1000	0	
	Filter Age	hrs	Client Info		0	0	
	Oil Changed		Client Info		Not Changd	Changed	
	Filter Changed		Client Info		Not Changd	Not Changd	
	Sample Status				NORMAL	NORMAL	
WEAR	Iron	ppm	ASTM D5185m	>900	47	70	
All component wear rates are normal.	Chromium	ppm	ASTM D5185m	>20	<1	1	
	Nickel	ppm	ASTM D5185m	>10	<1	<1	
	Titanium	ppm	ASTM D5185m		<1	0	
	Silver	ppm	ASTM D5185m		<1	0	
	Aluminum	ppm	ASTM D5185m	>30	<1	<1	
	Lead	ppm	ASTM D5185m	>50	<1	0	
	Copper	ppm	ASTM D5185m	>150	2	<1	
	Tin	ppm	ASTM D5185m	>20	<1	0	
	Vanadium	ppm	ASTM D5185m		0	0	
	White Metal	scalar	*Visual	NONE	NONE	LIGHT	
	Yellow Metal	scalar	*Visual	NONE	NONE	NONE	
CONTAMINATION	Silicon	ppm	ASTM D5185m	>50	3	3	
There is no indication of any contamination in the oil.	Potassium	ppm	ASTM D5185m		2	0	
	Water		WC Method	>0.2	NEG	NEG	
	Silt	scalar	*Visual	NONE	LIGHT	NONE	
	Debris	scalar	*Visual	NONE	NONE	NONE	
	Sand/Dirt	scalar	*Visual	NONE	NONE	NONE	
	Appearance	scalar	*Visual	NORML	NORML	NORML	
	Odor	scalar	*Visual	NORML	NORML	NORML	
	Emulsified Water	scalar	*Visual	>0.2	NEG	NEG	
FLUID CONDITION	Sodium	ppm	ASTM D5185m		0	1	
The condition of the oil is acceptable for the time in service.	Boron	ppm	ASTM D5185m		278	308	
	Barium	ppm	ASTM D5185m		5	0	
	Molybdenum	ppm	ASTM D5185m		1	2	
	Manganese	ppm	ASTM D5185m		2	5	
	Magnesium	ppm	ASTM D5185m		<1	2	
	Calcium	ppm	ASTM D5185m		19	35	
	Phosphorus	ppm	ASTM D5185m		1923	1289	
	Zinc	ppm	ASTM D5185m		19	24	
	Sulfur	ppm	ASTM D5185m		27254	25056	
	Visc @ 40°C	cSt	ASTM D445		52.5	102	





Certificate L2367

Laboratory Sample No.

: VCP417723 Lab Number : 06099452 Unique Number: 10897682 Test Package : MOBCE

: WearCheck USA - 501 Madison Ave., Cary, NC 27513 Received : 23 Feb 2024 **Tested** : 27 Feb 2024 Diagnosed

: 27 Feb 2024 - Don Baldridge

365 - ASCENDUM MACHINERY INC - SAVANNAH

54 MEDLINE DR RICHMOND HILL, GA

US 31324 Contact: JESSE WILSON

jesse.wilson@ascendummachinery.com

To discuss this sample report, contact Customer Service at 1-800-237-1369. * - Denotes test methods that are outside of the ISO 17025 scope of accreditation. Statements of conformity to specifications are based on the simple acceptance decision rule (JCGM 106:2012) F: (912)964-9515

T: