WEAR CONTAMINATION FLUID CONDITION

MARGINAL NORMAL NORMAL


Machine Id

TOLE_U4 TOLE_U4_P4

Non-Drive End Pump

ROYAL PURPLE SYNFILM GT 32 (2 OTS)

RECOMMENDATION	Test	UOM	Method	Limit/Abn	Current	History1	History2
No corrective action is recommended at this time. Resample at the next service interval to monitor.	Sample Number		Client Info		RP0025890	RP0034039	RP0026205
	Sample Date		Client Info		21 Feb 2024	16 Nov 2023	25 Sep 2023
	Machine Age	hrs	Client Info		0	0	0
	Oil Age	hrs	Client Info		0	0	0
	Filter Age	hrs	Client Info		0	0	0
	Oil Changed		Client Info		N/A	N/A	N/A
	Filter Changed		Client Info		N/A	N/A	N/A
	Sample Status				MARGINAL	MARGINAL	MARGINAL
WEAR	Iron	ppm	ASTM D5185m	>90	4	2	1
The copper level is abnormal. All other component wear rates are normal.	Chromium	ppm	ASTM D5185m	>5	0	0	0
	Nickel	ppm	ASTM D5185m	>5	0	<1	<1
	Titanium	ppm	ASTM D5185m	>3	0	0	0
	Silver	ppm	ASTM D5185m	>3	0	0	0
	Aluminum	ppm	ASTM D5185m	>7	0	<1	<1
	Lead	ppm	ASTM D5185m	>12	6	7	6
	Copper	ppm	ASTM D5185m	>30	△ 66	<u> </u>	<u>^</u> 70
	Tin	ppm	ASTM D5185m	>9	<1	2	2
	Vanadium	ppm	ASTM D5185m		0	0	0
	White Metal	scalar	*Visual	NONE	NONE	NONE	NONE
	Yellow Metal	scalar	*Visual	NONE	NONE	NONE	NONE
CONTAMINATION	Silicon	ppm	ASTM D5185m	>60	<1	1	<1
The water content is negligible. There is no indication of any contamination in the oil.	Potassium	ppm	ASTM D5185m	>20	0	<1	0
	Water	%	ASTM D6304	>.1	0.010	0.008	0.025
	ppm Water	ppm	ASTM D6304	>1000	102	83	254.6
	Silt	cooler	*) (')				
		scalar	*Visual	NONE	NONE	NONE	NONE
	Debris	scalar	*Visual	NONE	NONE NONE	NONE NONE	NONE
	Debris Sand/Dirt						
		scalar	*Visual	NONE	NONE	NONE	NONE
	Sand/Dirt	scalar scalar	*Visual	NONE NONE	NONE NONE	NONE NONE	NONE
	Sand/Dirt Appearance	scalar scalar scalar scalar	*Visual *Visual	NONE NONE NORML	NONE NONE NORML	NONE NONE NORML	NONE NONE NORML
FLUID CONDITION	Sand/Dirt Appearance Odor	scalar scalar scalar scalar	*Visual *Visual *Visual *Visual	NONE NORML NORML	NONE NONE NORML NORML	NONE NONE NORML	NONE NONE NORML
FLUID CONDITION The AN level is acceptable for this fluid. The condition of the cill is	Sand/Dirt Appearance Odor Emulsified Water	scalar scalar scalar scalar scalar	*Visual *Visual *Visual *Visual *Visual	NONE NORML NORML	NONE NONE NORML NORML NEG	NONE NONE NORML NORML NEG	NONE NONE NORML NORML NEG
FLUID CONDITION The AN level is acceptable for this fluid. The condition of the oil is acceptable for the time in service.	Sand/Dirt Appearance Odor Emulsified Water Sodium	scalar scalar scalar scalar scalar	*Visual *Visual *Visual *Visual *Visual *ASTM D5185m	NONE NORML NORML	NONE NONE NORML NORML NEG	NONE NONE NORML NORML NEG	NONE NORML NORML NEG
The AN level is acceptable for this fluid. The condition of the oil is	Sand/Dirt Appearance Odor Emulsified Water Sodium Boron Barium	scalar scalar scalar scalar scalar ppm	*Visual *Visual *Visual *Visual *Visual ASTM D5185m	NONE NORML NORML	NONE NORML NORML NEG <1	NONE NORML NORML NEG	NONE NORML NORML NEG
The AN level is acceptable for this fluid. The condition of the oil is	Sand/Dirt Appearance Odor Emulsified Water Sodium Boron	scalar scalar scalar scalar scalar ppm ppm	*Visual *Visual *Visual *Visual *Visual ASTM D5185m ASTM D5185m	NONE NORML NORML	NONE NORML NORML NEG <1 0	NONE NORML NORML NEG 1 0	NONE NORML NORML NEG 1 0 0
The AN level is acceptable for this fluid. The condition of the oil is	Sand/Dirt Appearance Odor Emulsified Water Sodium Boron Barium Molybdenum	scalar scalar scalar scalar scalar ppm ppm ppm	*Visual *Visual *Visual *Visual *Visual ASTM D5185m ASTM D5185m ASTM D5185m	NONE NORML NORML	NONE NORML NORML NEG <1 0 0	NONE NORML NORML NEG 1 0 0	NONE NORML NORML NEG 1 0 0
The AN level is acceptable for this fluid. The condition of the oil is	Sand/Dirt Appearance Odor Emulsified Water Sodium Boron Barium Molybdenum Manganese	scalar scalar scalar scalar scalar ppm ppm ppm ppm	*Visual *Visual *Visual *Visual *Visual ASTM D5185m ASTM D5185m ASTM D5185m ASTM D5185m ASTM D5185m	NONE NORML NORML	NONE NORML NORML NEG <1 0 0 0	NONE NORML NORML NEG 1 0 0 0	NONE NORML NORML NEG 1 0 0 0 <1
The AN level is acceptable for this fluid. The condition of the oil is	Sand/Dirt Appearance Odor Emulsified Water Sodium Boron Barium Molybdenum Manganese Magnesium	scalar scalar scalar scalar scalar ppm ppm ppm ppm ppm	*Visual *Visual *Visual *Visual *Visual ASTM D5185m	NONE NORML NORML	NONE NORML NORML NEG <1 0 0 0 62	NONE NORML NORML NEG 1 0 0 0 0 66	NONE NORML NORML NEG 1 0 0 0 <1 53
The AN level is acceptable for this fluid. The condition of the oil is	Sand/Dirt Appearance Odor Emulsified Water Sodium Boron Barium Molybdenum Manganese Magnesium Calcium	scalar scalar scalar scalar scalar ppm ppm ppm ppm ppm	*Visual *Visual *Visual *Visual *Visual ASTM D5185m	NONE NORML NORML	NONE NORML NORML NEG <1 0 0 0 62 <1	NONE NORML NORML NEG 1 0 0 0 66 2	NONE NORML NORML NEG 1 0 0 <1 53 2
The AN level is acceptable for this fluid. The condition of the oil is	Sand/Dirt Appearance Odor Emulsified Water Sodium Boron Barium Molybdenum Manganese Magnesium Calcium Phosphorus	scalar scalar scalar scalar scalar ppm ppm ppm ppm ppm ppm ppm	*Visual *Visual *Visual *Visual *Visual *Visual ASTM D5185m ASTM D5185m	NONE NORML NORML	NONE NORML NORML NEG <1 0 0 0 4 62 <1 4	NONE NORML NORML NEG 1 0 0 0 66 2 4	NONE NORML NORML NEG 1 0 0 0 <1 53 2 1







Certificate L2367

Laboratory Sample No.

Lab Number : 06101713

: RP0025890 Unique Number: 10899943 Test Package : PLANT

: WearCheck USA - 501 Madison Ave., Cary, NC 27513 Received : 27 Feb 2024

Tested : 29 Feb 2024 : 29 Feb 2024 - Jonathan Hester Diagnosed

ENERGY TRANSFER - TOLEDO

2549 BROWN ROAD OREGON, OH US 43616

T: (419)389-7403

Contact: DARREN GRANT

To discuss this sample report, contact Customer Service at 1-800-237-1369.

* - Denotes test methods that are outside of the ISO 17025 scope of accreditation. Statements of conformity to specifications are based on the simple acceptance decision rule (JCGM 106:2012)

F: