WEAR CONTAMINATION FLUID CONDITION **NORMAL NORMAL NORMAL**

[SPM674034]

SENNEBOGEN 835E 835.0.3239

Component
Rear Axle

RECOMMENDATION Resample at the next service interval to monitor.	Test	UOM	Method	Limit/Abn	Current	History1	History2
	Sample Number		Client Info	2	VCP429212		
	Sample Date		Client Info		15 Feb 2024		
	Machine Age	hrs	Client Info		991		
	Oil Age	hrs	Client Info		0		
	Filter Age	hrs	Client Info		0		
	Oil Changed		Client Info		Changed		
	Filter Changed		Client Info		Not Changd		
	Sample Status				NORMAL		
WEAR	Iron	ppm	ASTM D5185m	>500	85		
All component wear rates are normal.	Chromium	ppm	ASTM D5185m	>10	<1		
	Nickel	ppm	ASTM D5185m	>10	0		
	Titanium	ppm	ASTM D5185m		0		
	Silver	ppm	ASTM D5185m		0		
	Aluminum	ppm	ASTM D5185m	>25	<1		
	Lead	ppm	ASTM D5185m	>25	0		
	Copper	ppm	ASTM D5185m	>50	60		
	Tin	ppm	ASTM D5185m	>10	0		
	Vanadium	ppm	ASTM D5185m		0		
	White Metal	scalar	*Visual	NONE	MODER		
	Yellow Metal	scalar	*Visual	NONE	NONE		
CONTAMINATION	Silicon	ppm	ASTM D5185m	>75	4		
There is no indication of any contamination in the oil.	Potassium	ppm	ASTM D5185m	>20	<1		
	Water		WC Method	>0.2	NEG		
	Silt	scalar	*Visual	NONE	NONE		
	Debris	scalar	*Visual	NONE	NONE		
	Sand/Dirt	scalar	*Visual	NONE	NONE		
	Appearance	scalar	*Visual	NORML	NORML		
	Odor	scalar	*Visual	NORML	NORML		
	Emulsified Water	scalar	*Visual	>0.2	NEG		
FLUID CONDITION	Sodium	ppm	ASTM D5185m	>170	6		
The condition of the oil is acceptable for the time in service.	Boron	ppm	ASTM D5185m	400	135		
	Barium	ppm	ASTM D5185m	200	5		
	Molybdenum	ppm	ASTM D5185m	12	0		
	Manganese	ppm	ASTM D5185m		3		
	Magnesium	ppm	ASTM D5185m	12	2		
	Calcium	ppm	ASTM D5185m		11		
	Phosphorus	ppm	ASTM D5185m		1849		
	Zinc	ppm	ASTM D5185m		37		
	Sulfur	ppm	ASTM D5185m	22500	31497		





Certificate L2367

Report Id: BELBOU [WUSCAR] 06101993 (Generated: 02/29/2024 16:05:50) Rev: 1

Laboratory Sample No.

Lab Number : 06101993 Unique Number : 10900223 Test Package : MOB 1

: WearCheck USA - 501 Madison Ave., Cary, NC 27513 : VCP429212

To discuss this sample report, contact Customer Service at 1-800-237-1369.

Received : 27 Feb 2024 **Tested** : 28 Feb 2024 Diagnosed

: 29 Feb 2024 - Jonathan Hester

BOURBONNAIS, IL US 60914 Contact: M. POZAN mpozan@belsonsteel.com T: (815)932-7416

BELSON STEEL

1685 N STATE RTE 50

* - Denotes test methods that are outside of the ISO 17025 scope of accreditation. Statements of conformity to specifications are based on the simple acceptance decision rule (JCGM 106:2012)

Contact/Location: M. POZAN - BELBOU