

## RECOMMENDATION

Resample at the next service interval to monitor.

## **WEAR**

All component wear rates are normal.

## CONTAMINATION

There is no indication of any contamination in the oil.

## FLUID CONDITION

The condition of the oil is acceptable for the time in service.

Test	UOM	Method	Limit/Abn	Current	History1	History2
Sample Number		Client Info		ASC0007648		
Sample Date		Client Info		26 Feb 2024		
Machine Age	hrs	Client Info		470		
Oil Age	hrs	Client Info		470		
Filter Age	hrs	Client Info		0		
Oil Changed		Client Info		Not Changd		
Filter Changed		Client Info		N/A		
Sample Status				NORMAL		
Iron	ppm	ASTM D5185m	>500	48		
Chromium	ppm	ASTM D5185m	>20	<1		
Nickel	ppm	ASTM D5185m	>10	0		
Titanium	ppm	ASTM D5185m		0		
Silver	ppm	ASTM D5185m		0		
Aluminum	ppm	ASTM D5185m	>30	<1		
Lead	ppm	ASTM D5185m	>50	<1		
Copper	ppm	ASTM D5185m	>120	0		
Tin	ppm	ASTM D5185m	>20	0		
Vanadium	ppm	ASTM D5185m		<1		
White Metal	scalar	*Visual	NONE	NONE		
Yellow Metal	scalar	*Visual	NONE	NONE		
Silicon	ppm	ASTM D5185m	>50	11		
Potassium	ppm	ASTM D5185m	>20	1		
Water		WC Method	>0.2	NEG		
Silt	scalar	*Visual	NONE	NONE		
Silt Debris	scalar	*Visual *Visual	NONE NONE	NONE		
Silt Debris Sand/Dirt	scalar scalar	*Visual *Visual *Visual	NONE NONE NONE	NONE NONE NONE		
Silt Debris Sand/Dirt Appearance	scalar scalar scalar	*Visual *Visual *Visual *Visual	NONE NONE NORML	NONE NONE NORML		  
Silt Debris Sand/Dirt Appearance Odor	scalar scalar scalar scalar	*Visual *Visual *Visual *Visual *Visual	NONE NONE NORML NORML	NONE NONE NORML NORML		
Silt Debris Sand/Dirt Appearance	scalar scalar scalar	*Visual *Visual *Visual *Visual	NONE NONE NORML	NONE NONE NORML		  
Silt Debris Sand/Dirt Appearance Odor	scalar scalar scalar scalar	*Visual *Visual *Visual *Visual *Visual	NONE NONE NORML NORML	NONE NONE NORML NORML		  
Silt Debris Sand/Dirt Appearance Odor Emulsified Water	scalar scalar scalar scalar scalar	*Visual *Visual *Visual *Visual *Visual *Visual	NONE NONE NORML NORML	NONE NONE NORML NORML NEG	   	
Silt Debris Sand/Dirt Appearance Odor Emulsified Water Sodium	scalar scalar scalar scalar scalar ppm	*Visual *Visual *Visual *Visual *Visual ASTM D5185m	NONE NONE NORML NORML	NONE NONE NORML NORML NEG	   	
Silt Debris Sand/Dirt Appearance Odor Emulsified Water Sodium Boron	scalar scalar scalar scalar scalar ppm	*Visual *Visual *Visual *Visual *Visual *Visual ASTM D5185m ASTM D5185m	NONE NONE NORML NORML	NONE NONE NORML NORML NEG 1 117		
Silt Debris Sand/Dirt Appearance Odor Emulsified Water Sodium Boron Barium	scalar scalar scalar scalar scalar ppm ppm	*Visual *Visual *Visual *Visual *Visual ASTM D5185m ASTM D5185m	NONE NONE NORML NORML	NONE NONE NORML NORML NEG 1 117 0		
Silt Debris Sand/Dirt Appearance Odor Emulsified Water Sodium Boron Barium Molybdenum	scalar scalar scalar scalar ppm ppm ppm	*Visual *Visual *Visual *Visual *Visual *Visual ASTM D5185m ASTM D5185m ASTM D5185m	NONE NONE NORML NORML	NONE NONE NORML NORML NEG 1 117 0 2		
Silt Debris Sand/Dirt Appearance Odor Emulsified Water Sodium Boron Barium Molybdenum Manganese	scalar scalar scalar scalar ppm ppm ppm ppm	*Visual *Visual *Visual *Visual *Visual *Visual ASTM D5185m ASTM D5185m ASTM D5185m ASTM D5185m	NONE NONE NORML NORML	NONE NONE NORML NORML NEG 1 117 0 2 2		
Silt Debris Sand/Dirt Appearance Odor Emulsified Water Sodium Boron Barium Molybdenum Manganese Magnesium	scalar scalar scalar scalar ppm ppm ppm ppm ppm	*Visual *Visual *Visual *Visual *Visual ASTM D5185m ASTM D5185m ASTM D5185m ASTM D5185m ASTM D5185m	NONE NONE NORML NORML	NONE NONE NORML NORML NEG 1 1117 0 2 2 2 9		
Silt Debris Sand/Dirt Appearance Odor Emulsified Water Sodium Boron Barium Molybdenum Manganese Magnesium Calcium	scalar scalar scalar scalar ppm ppm ppm ppm ppm ppm	*Visual *Visual *Visual *Visual *Visual *Visual ASTM D5185m ASTM D5185m ASTM D5185m ASTM D5185m ASTM D5185m ASTM D5185m	NONE NONE NORML NORML	NONE NONE NORML NORML NEG 1 117 0 2 2 2 9 4030		

Visc @ 40°C

cSt


ASTM D445

55

Submitted By: KARRINGTON RENDLEMAN

41.0

WEAR NORMAL CONTAMINATION NORMAL FLUID CONDITION NORMAL



() 00 52 .) ಸ್ಪ 50 42 40 38 36 Abnorma 34 Feb26/24 Feb26/24



114 - ASCENDUM MACHINERY INC - CONCORD : WearCheck USA - 501 Madison Ave., Cary, NC 27513 1025 INTERNATIONAL DR NW CONCORD, NC : 02 Mar 2024 - Wes Davis US 28027 Contact: JEFF WILBANKS jeff.wilbanks@ascendummachinery.com T: (704)599-8179 F: (704)596-1362

To discuss this sample report, contact Customer Service at 1-800-237-1369. \* - Denotes test methods that are outside of the ISO 17025 scope of accreditation.

: ASC0007648

Statements of conformity to specifications are based on the simple acceptance decision rule (JCGM 106:2012)

Received

Diagnosed

Tested

: 29 Feb 2024

: 02 Mar 2024

Certificate L2367

Laboratory

Sample No.

Lab Number : 06105607

Unique Number : 10903837

Test Package : CONST

Submitted By: KARRINGTON RENDLEMAN

Page 2 of 2