WEAR CONTAMINATION FLUID CONDITION

NORMAL NORMAL



[SWA491951 RENTAL]
Machine Id
VOLVO DD120C 288138

Component Rear Left Final Drive

VOLVO SHC 630 ( GAL)							
RECOMMENDATION	Test	UOM	Method	Limit/Abn	Current	History1	History2
Resample at the next service interval to monitor.	Sample Number		Client Info		VCP434375		
	Sample Date		Client Info		26 Feb 2024		
	Machine Age	hrs	Client Info		4350		
	Oil Age	hrs	Client Info		1000		
	Filter Age	hrs	Client Info		0		
	Oil Changed		Client Info		Changed		
	Filter Changed		Client Info		Not Changd		
	Sample Status				NORMAL		
WEAR	Iron	ppm	ASTM D5185m	>500	388		
All component wear rates are normal.	Chromium	ppm	ASTM D5185m	>10	4		
	Nickel	ppm	ASTM D5185m	>10	<1		
	Titanium	ppm	ASTM D5185m		0		
	Silver	ppm	ASTM D5185m		0		
	Aluminum	ppm	ASTM D5185m	>25	<1		
	Lead	ppm	ASTM D5185m	>25	0		
	Copper	ppm	ASTM D5185m	>50	0		
	Tin	ppm	ASTM D5185m	>10	0		
	Vanadium	ppm	ASTM D5185m		0		
	White Metal	scalar	*Visual	NONE	MODER		
	Yellow Metal	scalar	*Visual	NONE	NONE		
CONTAMINATION	Silicon	ppm	ASTM D5185m	>75	25		
There is no indication of any contamination in the oil.	Potassium	ppm	ASTM D5185m		5		
	Water			>0.2	NEG		
	Silt	scalar	*Visual	NONE	MODER		
	Debris	scalar	*Visual	NONE	NONE		
	Sand/Dirt	scalar	*Visual	NONE	NONE		
	Appearance	scalar	*Visual	NORML	NORML		
	Odor	scalar	*Visual	NORML	NORML		
	Emulsified Water	scalar	*Visual	>0.2	NEG		
FLUID CONDITION	Sodium	ppm	ASTM D5185m		3		
The condition of the oil is acceptable for the time in service.	Boron	ppm	ASTM D5185m		0		
	Barium	ppm	ASTM D5185m		0		
	Molybdenum	ppm	ASTM D5185m		<1		
	Manganese	ppm	ASTM D5185m		5		
	Magnesium	ppm	ASTM D5185m		1		
	Calcium	ppm	ASTM D5185m		26		
	Phosphorus	ppm	ASTM D5185m		334		
	Zinc	ppm	ASTM D5185m		34		
	Sulfur	ppm	ASTM D5185m		487		
	Visc @ 40°C	cSt	ASTM D445		210		







Certificate L2367

Laboratory Sample No.

Lab Number : 06106453 Unique Number : 10909950 Test Package : MOB 1

: VCP434375

: WearCheck USA - 501 Madison Ave., Cary, NC 27513 Received : 01 Mar 2024 **Tested** Diagnosed

: 04 Mar 2024

: 05 Mar 2024 - Jonathan Hester

**ALTA EQUIPMENT** 5985 COURT STREET ROAD SYRACUSE, NY US 13206

Contact: JIM STRIGLE JIM.STRIGLE@ALTG.COM T: (315)437-2611

To discuss this sample report, contact Customer Service at 1-800-237-1369. \* - Denotes test methods that are outside of the ISO 17025 scope of accreditation.

Statements of conformity to specifications are based on the simple acceptance decision rule (JCGM 106:2012)

F: (315)434-9471