

WEAR CONTAMINATION **FLUID CONDITION**


NORMAL NORMAL NORMAL

FORD 846-5157

Component

1 Gasoline Engine

DECOMMENDATION	- .			1.1. 1.741	()	L	
RECOMMENDATION	Test	UOM	Method	Limit/Abn	Current	History1	History2
Resample at the next service interval to monitor.	Sample Number		Client Info		RPL0019448		
	Sample Date	and a	Client Info		06 Mar 2024		
	Machine Age	mls	Client Info		10905		
	Oil Age	mls	Client Info		10905		
	Filter Age	mls	Client Info		10905		
	Oil Changed		Client Info		Not Changd		
	Filter Changed		Client Info		Not Changd		
	Sample Status				NORMAL		
WEAR	Iron	ppm	ASTM D5185m	>150	21		
	Chromium	ppm	ASTM D5185m	>20	<1		
All component wear rates are normal.	Nickel	ppm	ASTM D5185m		<1		
	Titanium	ppm	ASTM D5185m		<1		
	Silver	ppm	ASTM D5185m	>2	0		
	Aluminum	ppm	ASTM D5185m		10		
	Lead	ppm	ASTM D5185m		<1		
	Copper	ppm	ASTM D5185m		49		
	Tin	ppm	ASTM D5185m		<1		
	Vanadium	ppm	ASTM D5185m		0		
	White Metal	scalar	*Visual	NONE	NONE		
	Yellow Metal	scalar	*Visual	NONE	NONE		
CONTAMINATION	0		AOTM DEGOE				
	Silicon	ppm	ASTM D5185m		47		
There is no indication of any contamination in the oil.	Potassium	ppm	ASTM D5185m		5		
	Fuel		WC Method	>4.0	<1.0		
	Water		WC Method	>0.2	NEG		
	Glycol	0/			NEG		
	Soot % Nitration	%	*ASTM D7844 *ASTM D7624	. 20	0		
		Abs/tmm		>20	10.7		
	Sulfation	Abs/.1mm	*ASTM D7415		25.5 NONE		
	Silt Debris	scalar	*Visual	NONE	NONE		
		scalar	*Visual	NONE	NONE		
	Sand/Dirt	scalar		NONE	NONE		
	Appearance Odor	scalar scalar	*Visual *Visual	NORML NORML	NORML NORML		
	Emulsified Water		*Visual	>0.2	NEG		
<u></u>		Scalai	Visuai	>0.2			
FLUID CONDITION	Sodium	ppm	ASTM D5185m	>400	6		
	Boron	ppm	ASTM D5185m		27		
The BN result indicates that there is suitable alkalinity remaining in the oil. The condition of the oil is suitable for further service.	Barium	ppm	ASTM D5185m		<1		
	Molybdenum	ppm	ASTM D5185m		148		
	Manganese	ppm	ASTM D5185m		11		
	Magnesium	ppm	ASTM D5185m		378		
	Calcium	ppm	ASTM D5185m		1239		
	Phosphorus	ppm	ASTM D5185m		652		
	Zinc	ppm	ASTM D5185m		786		
	Sulfur	ppm	ASTM D5185m		2715		
	Oxidation	Abs/.1mm	*ASTM D7414	>25	18.2		
	Base Number (BN)	mg KOH/g	ASTM D2896	6.7	4.2		
	Visc @ 100°C	cSt	ASTM D445	11.1	9.3		







Certificate L2367

Report Id: PAC7006 [WUSCAR] 06121959 (Generated: 03/19/2024 18:30:57) Rev: 1

Laboratory Sample No.

: RPL0019448 Lab Number : 06121959 Unique Number : 10936110 Test Package : FLEET

: WearCheck USA - 501 Madison Ave., Cary, NC 27513 Received : 19 Mar 2024 **Tested**

: 19 Mar 2024 : 19 Mar 2024 - Wes Davis Diagnosed

RTL PACLEASE - 7006 - Pico Rivera

7837 Telegraph Rd Pico Rivera, CA US 90660

Contact: GERARDO CARROLA carrolag@rushenterprises.com

To discuss this sample report, contact Customer Service at 1-800-237-1369. * - Denotes test methods that are outside of the ISO 17025 scope of accreditation.

Statements of conformity to specifications are based on the simple acceptance decision rule (JCGM 106:2012)

Submitted By: TECHNICIAN ACCOUNT

T:

F: