**WEAR CONTAMINATION FLUID CONDITION**  **NORMAL NORMAL NORMAL** 

## [687940 ATLAS ORG] **VOLVO L70 624147**

Component Rear Axle

RECOMMENDATION	Test	UOM	Method	Limit/Abn	Current	History1	History2
Resample at the next service interval to monitor.	Sample Number	OOW	Client Info	LITTIU/ADIT	VCP441511		
	Sample Date		Client Info		13 Mar 2024		
	Machine Age	hrs	Client Info		5718		
	Oil Age	hrs	Client Info		0		
	Filter Age	hrs	Client Info		0		
	Oil Changed		Client Info		Not Changd		
	Filter Changed		Client Info		Not Changd		
	Sample Status				NORMAL		
A/C A D							
WEAR	Iron	ppm	ASTM D5185m		178		
All component wear rates are normal.	Chromium	ppm	ASTM D5185m		3		
	Nickel	ppm	ASTM D5185m	>10	2		
	Titanium	ppm	ASTM D5185m		<1		
	Silver	ppm	ASTM D5185m		0		
	Aluminum	ppm	ASTM D5185m		4		
	Lead	ppm	ASTM D5185m		<1		
	Copper	ppm	ASTM D5185m		25		
	Tin	ppm	ASTM D5185m	>20	3		
	Vanadium	ppm	ASTM D5185m	NONE	<1		
	White Metal	scalar	*Visual	NONE	NONE		
	Yellow Metal	scalar	*Visual	NONE	NONE		
CONTAMINATION	Silicon	ppm	ASTM D5185m	>50	18		
There is no indication of any contamination in the oil.	Potassium	ppm	ASTM D5185m	>20	3		
	Water		WC Method	>0.2	NEG		
	Silt	scalar	*Visual	NONE	NONE		
	Debris	scalar	*Visual	NONE	NONE		
	Sand/Dirt	scalar	*Visual	NONE	NONE		
	Appearance	scalar	*Visual	NORML	NORML		
	Odor	scalar	*Visual	NORML	NORML		
	<b>Emulsified Water</b>	scalar	*Visual	>0.2	NEG		
FLUID CONDITION	Sodium	nnm	ASTM D5185m		2		
The condition of the oil is acceptable for the time in service.	Boron	ppm	ASTM D5185m	100	21		
	Barium	ppm	ASTM D5185m		0		
	Molybdenum	ppm	ASTM D5185m		5		
	Manganese	ppm	ASTM D5185m	U	5		
	Magnesium	ppm	ASTM D5185m	0	19		
	Calcium	ppm	ASTM D5185m		2736		
	Phosphorus	ppm	ASTM D5185m		983		
	Zinc	ppm	ASTM D5185m		1191		
	Sulfur	ppm	ASTM D5185m		3714		
	Visc @ 40°C	cSt	ASTM D3103III		50.7		





Certificate L2367

Laboratory Sample No. Lab Number : 06124016

: VCP441511 Unique Number: 10938167 Test Package : MOB 1

: WearCheck USA - 501 Madison Ave., Cary, NC 27513 Received : 20 Mar 2024 **Tested** : 21 Mar 2024

: 22 Mar 2024 - Don Baldridge Diagnosed

ALTA EQUIPMENT/FLAGLER EQUIPMENT LLC 9601 BOGGY CREEK RD

ORLANDO, FL US 32824 Contact: Robert LaPlante

robert.laplante@altg.com T: (407)508-9736

F: (407)659-8720

To discuss this sample report, contact Customer Service at 1-800-237-1369.

\* - Denotes test methods that are outside of the ISO 17025 scope of accreditation.

Statements of conformity to specifications are based on the simple acceptance decision rule (JCGM 106:2012)