

Machine Id **145374** Component **Right Steering** Fluid LIEBHERR GEAR BASIC 90 LS (--- GAL)

RECOMMENDATION

The fluid change at the time of sampling has been noted. We advise that you inspect for the source(s) of wear. We recommend an early resample to monitor this condition.

WEAR

The iron level is severe.

CONTAMINATION


There is no indication of any contamination in the fluid.


FLUID CONDITION

The fluid is no longer serviceable as a result of the abnormal and/or severe wear.

Test	UOM	Method	Limit/Abn	Current	History1	History2
Sample Number		Client Info		LM0001042		
Sample Date		Client Info		16 Mar 2024		
Machine Age	hrs	Client Info		5931		
Oil Age	hrs	Client Info		1000		
Filter Age	hrs	Client Info		1000		
Oil Changed		Client Info		Changed		
Filter Changed		Client Info		Changed		
Sample Status				SEVERE		
Iron	ppm	ASTM D5185m	>60	▲ 612		
Chromium	ppm	ASTM D5185m	>12	3		
Nickel	ppm	ASTM D5185m	>6	0		
Titanium	ppm	ASTM D5185m		0		
Silver	ppm	ASTM D5185m		0		
Aluminum	ppm	ASTM D5185m	>4	0		
Lead	ppm	ASTM D5185m	>12	0		
Copper	ppm	ASTM D5185m	>30	2		
Tin	ppm	ASTM D5185m		0		
Vanadium	ppm	ASTM D5185m		0		
White Metal	scalar	*Visual	NONE	NONE		
Yellow Metal	scalar	*Visual	NONE	NONE		
Silicon	ppm	ASTM D5185m	>10	4		
Potassium	ppm	ASTM D5185m	>20	0		
Water		WC Method		NEG		
Water Silt	scalar	WC Method *Visual	NONE	NEG NONE		
	scalar scalar		NONE			
Silt		*Visual	_	NONE		
Silt Debris	scalar	*Visual *Visual	NONE	NONE		
Silt Debris Sand/Dirt	scalar scalar	*Visual *Visual *Visual	NONE	NONE NONE NONE		
Silt Debris Sand/Dirt Appearance	scalar scalar scalar	*Visual *Visual *Visual *Visual	NONE NONE NORML	NONE NONE NONE NORML		
Silt Debris Sand/Dirt Appearance Odor Emulsified Water	scalar scalar scalar scalar	*Visual *Visual *Visual *Visual *Visual *Visual	NONE NONE NORML	NONE NONE NORML NORML NEG		
Silt Debris Sand/Dirt Appearance Odor Emulsified Water Sodium	scalar scalar scalar scalar	*Visual *Visual *Visual *Visual *Visual *Visual ASTM D5185m	NONE NORML NORML	NONE NONE NORML NORML NEG 2		
Silt Debris Sand/Dirt Appearance Odor Emulsified Water Sodium Boron	scalar scalar scalar scalar scalar	*Visual *Visual *Visual *Visual *Visual *Visual ASTM D5185m	NONE NONE NORML	NONE NONE NORML NORML NEG		
Silt Debris Sand/Dirt Appearance Odor Emulsified Water Sodium Boron Barium	scalar scalar scalar scalar scalar ppm	*Visual *Visual *Visual *Visual *Visual ASTM D5185m ASTM D5185m	NONE NORML NORML	NONE NONE NORML NORML NEG 2 0 0		
Silt Debris Sand/Dirt Appearance Odor Emulsified Water Sodium Boron Barium Molybdenum	scalar scalar scalar scalar scalar ppm ppm	*Visual *Visual *Visual *Visual *Visual *Visual ASTM D5185m ASTM D5185m ASTM D5185m	NONE NORML NORML 0 0	NONE NONE NORML NORML NEG 2 0 0 0		
Silt Debris Sand/Dirt Appearance Odor Emulsified Water Sodium Boron Barium Molybdenum Manganese	scalar scalar scalar scalar scalar ppm ppm	*Visual *Visual *Visual *Visual *Visual *Visual ASTM D5185m ASTM D5185m ASTM D5185m ASTM D5185m	NONE NORML NORML 0 0 0 0	NONE NONE NORML NORML NEG 2 0 0 0 0 5		
Silt Debris Sand/Dirt Appearance Odor Emulsified Water Sodium Boron Barium Molybdenum Manganese Magnesium	scalar scalar scalar scalar scalar ppm ppm ppm	*Visual *Visual *Visual *Visual *Visual *Visual ASTM D5185m ASTM D5185m ASTM D5185m ASTM D5185m ASTM D5185m	NONE NORML NORML O 0 0 0 0 0 2	NONE NONE NORML NORML NEG 2 0 0 0 0 5 0		
Silt Debris Sand/Dirt Appearance Odor Emulsified Water Sodium Boron Barium Molybdenum Manganese Magnesium Calcium	scalar scalar scalar scalar ppm ppm ppm ppm	*Visual *Visual *Visual *Visual *Visual *Visual ASTM D5185m ASTM D5185m ASTM D5185m ASTM D5185m ASTM D5185m ASTM D5185m	NONE NORML NORML 0 0 0 0 0 0 0 4 1	NONE NONE NORML NORML NEG 2 0 0 0 0 5 0 0 5 0 10		
Silt Debris Sand/Dirt Appearance Odor Emulsified Water Sodium Boron Barium Molybdenum Manganese Magnesium Calcium	scalar scalar scalar scalar ppm ppm ppm ppm ppm	*Visual *Visual *Visual *Visual *Visual *Visual *Visual ASTM D5185m ASTM D5185m ASTM D5185m ASTM D5185m ASTM D5185m ASTM D5185m	NONE NORML NORML O 0 0 0 0 0 2	NONE NONE NORML NORML NEG 2 0 0 0 0 5 0		
Silt Debris Sand/Dirt Appearance Odor Emulsified Water Sodium Boron Barium Malybdenum Manganese Magnesium Calcium Phosphorus Zinc	scalar scalar scalar scalar ppm ppm ppm ppm ppm ppm	*Visual *Visual *Visual *Visual *Visual *Visual *Visual ASTM D5185m ASTM D5185m ASTM D5185m ASTM D5185m ASTM D5185m ASTM D5185m ASTM D5185m	NONE NORML NORML 0 0 0 0 0 0 0 1 2 1 2 143 <1	NONE NONE NORML NORML NEG 2 0 0 0 0 0 5 0 0 10 2387 4		
Silt Debris Sand/Dirt Appearance Odor Emulsified Water Sodium Boron Barium Molybdenum Manganese Magnesium Calcium	scalar scalar scalar scalar ppm ppm ppm ppm ppm ppm	*Visual *Visual *Visual *Visual *Visual *Visual *Visual ASTM D5185m ASTM D5185m ASTM D5185m ASTM D5185m ASTM D5185m ASTM D5185m	NONE NORML NORML 0 0 0 0 0 0 1 1 <1 2143	NONE NONE NORML NORML NEG 2 0 0 0 0 5 0 10 2387		

Contact/Location: RONNY FUNK - LIEHIA





LIEBHERR USA CO - Maritime Cranes 15101 NW 112TH AVE HIALEAH GARDENS, FL : 23 Mar 2024 - Don Baldridge US 33018 Contact: RONNY FUNK ronny.funk@liebherr.com T: (305)817-7566 F:



Unique Number : 10938564 Diagnosed Test Package : CONST Certificate L2367 To discuss this sample report, contact Customer Service at 1-800-237-1369. * - Denotes test methods that are outside of the ISO 17025 scope of accreditation. Statements of conformity to specifications are based on the simple acceptance decision rule (JCGM 106:2012)

Received

Tested

: 20 Mar 2024

: 21 Mar 2024

Laboratory

Sample No.

Lab Number : 06124413

: LM0001042

Contact/Location: RONNY FUNK - LIEHIA

Page 2 of 2