

# Ascendum Machinery

SENNEBOGEN 821E RTH6 (S/N 82102749)

**Rear Axle** 

# VOLVO SUPER GEAR OIL 75W-80-GO102 (--- GAL)

RECOMMENDATIC	N
---------------	---

Resample at the next service interval to monitor.

#### **WEAR**

All component wear rates are normal.

### CONTAMINATION

There is no indication of any contamination in the oil.


## FLUID CONDITION


The condition of the oil is acceptable for the time in service.

~ = )						
Test	UOM	Method	Limit/Abn	Current	History1	History2
Sample Number		Client Info		ASC0007090	VCP0006687	
Sample Date		Client Info		09 Apr 2024	11 Apr 2023	
Machine Age	hrs	Client Info		2587	1939	
Oil Age	hrs	Client Info		648	1939	
Filter Age	hrs	Client Info		0	0	
Oil Changed		Client Info		Not Changd	Changed	
Filter Changed		Client Info		None	N/A	
Sample Status				NORMAL	NORMAL	
Iron	ppm	ASTM D5185m	>500	2	10	
Chromium	ppm	ASTM D5185m	>10	0	<1	
Nickel	ppm	ASTM D5185m	>10	0	<1	
Titanium	ppm	ASTM D5185m		0	0	
Silver	ppm	ASTM D5185m		0	0	
Aluminum	ppm	ASTM D5185m	>25	0	1	
Lead	ppm	ASTM D5185m	>25	0	0	
Copper	ppm	ASTM D5185m	>50	0	7	
Tin	ppm	ASTM D5185m	>10	0	0	
Vanadium	ppm	ASTM D5185m		0	0	
White Metal	scalar	*Visual	NONE	NONE	NONE	
Yellow Metal	scalar	*Visual	NONE	NONE	NONE	
Silicon	ppm	ASTM D5185m	>75	<1	11	
Potassium	ppm	ASTM D5185m	>20	0	2	
Water		WC Method	>0.2	NEG	NEG	
Silt	scalar	*Visual	NONE	NONE	NONE	
Debris	scalar	*Visual	NONE	NONE	NONE	
Sand/Dirt	scalar	*Visual	NONE	NONE	NONE	
Appearance	scalar	*Visual	NORML	NORML	NORML	
Odor	scalar	*Visual	NORML	NORML	NORML	
Emulsified Water	scalar	*Visual	>0.2	NEG	NEG	
Sodium	ppm	ASTM D5185m		2	17	
Boron	ppm	ASTM D5185m		225	127	
Barium	ppm	ASTM D5185m		0	0	
Molybdenum	ppm	ASTM D5185m		0	<1	
Manganese	ppm	ASTM D5185m		0	2	
Magnesium	ppm	ASTM D5185m		1	11	
Calcium	ppm	ASTM D5185m		286	3830	
Phosphorus	ppm	ASTM D5185m		2119	1240	
Zinc	ppm	ASTM D5185m		160	1522	
Sulfur	ppm	ASTM D5185m		26522	3241	
Visc @ 40°C	cSt	ASTM D445		51.7	55.3	
-						

Report Id: HILGREVC [WUSCAR] 06146208 (Generated: 04/12/2024 12:39:00) Rev: 1

Submitted By: KARRINGTON RENDLEMAN







PORT
NT RD
O, NC
27409
HEAD
rt.com
3-9441
8-9701
r1 }-

: WearCheck USA - 501 Madison Ave., Cary, NC 27513

Laboratory

Submitted By: KARRINGTON RENDLEMAN Page 2 of 2

HILCO TRANSPORT