WEAR CONTAMINATION FLUID CONDITION **NORMAL NORMAL NORMAL**

[41829 LANDMARK] **VOLVO A40G 352361**

Wet Disc Brake

RECOMMENDATION	Test	UOM	Method	Limit/Abn	Current	History1	History2
Resample at the next service interval to monitor.	Sample Number		Client Info		VCP449768		
	Sample Date		Client Info		12 Apr 2024		
	Machine Age	hrs	Client Info		3829		
	Oil Age	hrs	Client Info		0		
	Filter Age	hrs	Client Info		0		
	Oil Changed		Client Info		Changed		
	Filter Changed		Client Info		Changed		
	Sample Status				NORMAL		
WEAR	Iron	ppm	ASTM D5185m	>20	14		
All component wear rates are normal.	Chromium	ppm	ASTM D5185m		<1		
	Nickel	ppm	ASTM D5185m		2		
	Titanium	ppm	ASTM D5185m		0		
	Silver	ppm	ASTM D5185m		0		
	Aluminum	ppm	ASTM D5185m	>10	<1		
	Lead	ppm	ASTM D5185m	>10	<1		
	Copper	ppm	ASTM D5185m	>75	95		
	Tin	ppm	ASTM D5185m	>10	0		
	Vanadium	ppm	ASTM D5185m		<1		
	White Metal	scalar	*Visual	NONE	NONE		
	Yellow Metal	scalar	*Visual	NONE	NONE		
CONTAMINATION	Silicon	ppm	ASTM D5185m	> 20	15		
There is no indication of any contamination in the oil.	Potassium	ppm	ASTM D5185m		0		
	Water	PP	WC Method	>0.1	NEG		
	Silt	scalar	*Visual	NONE	NONE		
	Debris	scalar	*Visual	NONE	NONE		
	Sand/Dirt	scalar	*Visual	NONE	NONE		
	Appearance	scalar	*Visual	NORML	NORML		
	Odor	scalar	*Visual	NORML	NORML		
	Emulsified Water	scalar	*Visual	>0.1	NEG		
FLUID CONDITION	Sodium	ppm	ASTM D5185m		7		
The condition of the oil is acceptable for the time in service.	Boron	ppm	ASTM D5185m		127		
	Barium	ppm	ASTM D5185m		0		
	Molybdenum	ppm	ASTM D5185m		1		
	Manganese	ppm	ASTM D5185m		<1		
	Magnesium	ppm	ASTM D5185m		16		
	Calcium	ppm	ASTM D5185m		3916		
	Phosphorus	ppm	ASTM D5185m		1335		
	Zinc	ppm	ASTM D5185m		1612		
	Sulfur	ppm	ASTM D5185m		4962		
	Visc @ 40°C	cSt	ASTM D445	55	42.5		







Certificate L2367

Report Id: BALPARNC [WUSCAR] 06150703 (Generated: 04/18/2024 15:56:50) Rev: 1

Laboratory Sample No.

: VCP449768 Lab Number : 06150703 Unique Number : 10980781 Test Package : MOB 1

: WearCheck USA - 501 Madison Ave., Cary, NC 27513 Received : 16 Apr 2024

Tested : 17 Apr 2024 Diagnosed

: 18 Apr 2024 - Don Baldridge

BALFOUR BEATTY INFRASTRUCTURE INC

6701 OLD PLANK RD PARKTON, NC US 28371 Contact: Service Manager

To discuss this sample report, contact Customer Service at 1-800-237-1369.

* - Denotes test methods that are outside of the ISO 17025 scope of accreditation.

Statements of conformity to specifications are based on the simple acceptance decision rule (JCGM 106:2012)

T:

F: