



OIL ANALYSIS REPORT

WEAR	NORMAL
CONTAMINATION	NORMAL
FLUID CONDITION	NORMAL

Machine Id  
**SERVICIOS / EXTRACTION**  
 Component  
**Hydraulic System**  
 Fluid  
**ANDEROL BIO GUARD FRHF 46 (--- GAL)**

**RECOMMENDATION**

Resample at the next service interval to monitor.

Test	UOM	Method	Limit/Abn	Current	History1	History2
Sample Number		Client Info		<b>AN06151125</b>	AN06151113	AN06151101
Sample Date		Client Info		<b>12 Mar 2024</b>	23 Feb 2024	16 Jan 2024
Machine Age	hrs	Client Info		<b>0</b>	0	0
Oil Age	hrs	Client Info		<b>0</b>	0	0
Filter Age	hrs	Client Info		<b>0</b>	0	0
Oil Changed		Client Info		<b>N/A</b>	N/A	N/A
Filter Changed		Client Info		<b>N/A</b>	N/A	N/A
Sample Status				<b>NORMAL</b>	---	NORMAL

**WEAR**

All component wear rates are normal.

Iron	ppm	ASTM D5185m	>20	<b>0</b>	0	0
Chromium	ppm	ASTM D5185m	>20	<b>0</b>	0	0
Nickel	ppm	ASTM D5185m	>20	<b>&lt;1</b>	<1	<1
Titanium	ppm	ASTM D5185m		<b>0</b>	0	0
Silver	ppm	ASTM D5185m		<b>0</b>	0	0
Aluminum	ppm	ASTM D5185m	>20	<b>&lt;1</b>	<1	<1
Lead	ppm	ASTM D5185m	>20	<b>0</b>	0	0
Copper	ppm	ASTM D5185m	>20	<b>2</b>	2	2
Tin	ppm	ASTM D5185m	>20	<b>&lt;1</b>	<1	<1
Vanadium	ppm	ASTM D5185m		<b>0</b>	0	0
White Metal	scalar	*Visual	NONE	<b>NONE</b>	NONE	NONE
Yellow Metal	scalar	*Visual	NONE	<b>NONE</b>	NONE	NONE

**CONTAMINATION**











There is no indication of any contamination in the oil. The amount and size of particulates present in the system are acceptable.

Silicon	ppm	ASTM D5185m	>15	<b>0</b>	0	0
Potassium	ppm	ASTM D5185m	>20	<b>3</b>	2	2
Water	%	ASTM D6304	>0.05	<b>0.036</b>	0.034	0.034
ppm Water	ppm	ASTM D6304	>500	<b>365</b>	344	348
Particles >4µm		ASTM D7647	>5000	<b>4670</b>	1152	634
Particles >6µm		ASTM D7647	>1300	<b>949</b>	207	157
Particles >14µm		ASTM D7647	>160	<b>58</b>	16	22
Particles >21µm		ASTM D7647	>40	<b>14</b>	4	8
Particles >38µm		ASTM D7647	>10	<b>0</b>	1	1
Particles >71µm		ASTM D7647	>3	<b>0</b>	1	0
Oil Cleanliness		ISO 4406 (c)	>19/17/14	<b>19/17/13</b>	17/15/11	16/14/12
Silt	scalar	*Visual	NONE	<b>NONE</b>	NONE	NONE
Debris	scalar	*Visual	NONE	<b>NONE</b>	NONE	NONE
Sand/Dirt	scalar	*Visual	NONE	<b>NONE</b>	NONE	NONE
Appearance	scalar	*Visual	NORML	<b>NORML</b>	NORML	NORML
Odor	scalar	*Visual	NORML	<b>NORML</b>	NORML	NORML
Emulsified Water	scalar	*Visual	>0.05	<b>NEG</b>	NEG	NEG

**FLUID CONDITION**

The AN level is acceptable for this fluid. The condition of the oil is suitable for further service.

Sodium	ppm	ASTM D5185m		<b>2</b>	2	2
Boron	ppm	ASTM D5185m		<b>0</b>	0	0
Barium	ppm	ASTM D5185m		<b>0</b>	0	0
Molybdenum	ppm	ASTM D5185m		<b>0</b>	0	0
Manganese	ppm	ASTM D5185m		<b>1</b>	1	1
Magnesium	ppm	ASTM D5185m		<b>2</b>	1	2
Calcium	ppm	ASTM D5185m		<b>1</b>	1	1
Phosphorus	ppm	ASTM D5185m	196	<b>217</b>	209	221
Zinc	ppm	ASTM D5185m		<b>0</b>	0	0
Sulfur	ppm	ASTM D5185m	1440	<b>2344</b>	2199	2269
Acid Number (AN)	mg KOH/g	ASTM D8045	1	<b>1.24</b>	1.22	1.20
Visc @ 40°C	cSt	ASTM D445	45.41	<b>48.2</b>	48.3	48.2



**Laboratory** : WearCheck USA - 501 Madison Ave., Cary, NC 27513  
**Sample No.** : AN06151125 **Received** : 16 Apr 2024  
**Lab Number** : 06151125 **Tested** : 19 Apr 2024  
**Unique Number** : 10981203 **Diagnosed** : 19 Apr 2024 - Jonathan Hester  
**Test Package** : IND 2 ( Additional Tests: PrtCount )

**CONEXO INC**  
 2320 STARR LAKE DRIVE  
 ACWORTH, GA  
 US 30101  
 Contact: RICARDO HEIN  
 rhein@conexoinc.com  
 T: (678)806-0131  
 F: x:

Certificate L2367  
 To discuss this sample report, contact Customer Service at 1-800-237-1369.  
 \* - Denotes test methods that are outside of the ISO 17025 scope of accreditation.  
 Statements of conformity to specifications are based on the simple acceptance decision rule (JCGM 106:2012)