



# FUEL REPORT

CORROSION	<b>NORMAL</b>
CONTAMINANTS	<b>NORMAL</b>
FUEL CONDITION	<b>NORMAL</b>

Area

**[PMOAS53372432]**

Machine Id

**P1402200001 - UNIT 1**

Component

**Diesel Fuel**

Fluid

**No.2 DIESEL FUEL (LOW-SULPHUR) (--- GAL)**

## RECOMMENDATION

All laboratory tests indicate that this sample meets specifications for No.2 diesel fuel, ultra-low sulfur.

Test	UOM	Method	Limit/Abn	Current	History1	History2
Sample Number		Client Info		<b>DC0036987</b>	DC0029082	DC0019558
Sample Date		Client Info		<b>10 Apr 2024</b>	07 Apr 2023	02 May 2022
Machine Age	hrs	Client Info		<b>289</b>	252	222
Sample Status				<b>NORMAL</b>	NORMAL	NORMAL

## CORROSION

All metal levels are normal indicating no corrosion in the system.

Aluminum	ppm	ASTM D5185m	<0.1	<b>0</b>	0	0
Nickel	ppm	ASTM D5185m	<0.1	<b>0</b>	0	0
Lead	ppm	ASTM D5185m	<0.1	<b>0</b>	0	0
Vanadium	ppm	ASTM D5185m	<0.1	<b>0</b>	0	0
Iron	ppm	ASTM D5185m	<0.1	<b>0</b>	0	0

## CONTAMINANTS




The water content is negligible. There is no Bacteria, Yeast and/or Fungus indicated in the sample. There is no indication of any contamination in the fuel.

Silicon	ppm	ASTM D5185m	<1.0	<b>0</b>	0	0
Sodium	ppm	ASTM D5185m	<0.1	<b>&lt;1</b>	<1	0
Potassium	ppm	ASTM D5185m	<0.1	<b>&lt;1</b>	0	0
Water	%	ASTM D6304	<0.05	<b>0.003</b>	0.007	0.003
ppm Water	ppm	ASTM D6304	<500	<b>28</b>	76.8	25.7
% Gasoline	%	*In-House	<0.50	<b>0.0</b>	0.0	0.0
% Biodiesel	%	*In-House	<20.0	<b>0.0</b>	0.0	0.0
Calcium	ppm	ASTM D5185m	<0.1	<b>0</b>	0	0
Magnesium	ppm	ASTM D5185m	<0.1	<b>0</b>	0	0
Phosphorus	ppm	ASTM D5185m	<0.1	<b>0</b>	0	2
Zinc	ppm	ASTM D5185m	<0.1	<b>0</b>	0	0

## FUEL CONDITION

Sulfur value derived by ASTM D4294 method for ULSD validation. Sulfur level is acceptable for ULSD specification.

ASTM Color	scalar	*ASTM D1500		<b>L4.5</b>	L4.5	4.0
Visc @ 40°C	cSt	ASTM D445	3.0	<b>2.39</b>	3.3	2.45
Sulfur	ppm	ASTM D5185m	250	<b>0</b>	0	13
Sulfur (UVF)	ppm	ASTM D5453		<b>11</b>	10	12
API Gravity		ASTM D7777	37.7	<b>37.2</b>	32.4	37.2



Certificate L2367

**Laboratory** : WearCheck USA - 501 Madison Ave., Cary, NC 27513  
**Sample No.** : DC0036987 **Received** : 17 Apr 2024  
**Lab Number** : 06152456 **Tested** : 30 Apr 2024  
**Unique Number** : 10982534 **Diagnosed** : 06 May 2024 - Doug Bogart  
**Test Package** : DF-5 ( Additional Tests: API, Cetane, Fuel, Screen )

**KELLY GENERATOR & EQUIPMENT INC**  
 1955 DALE LN  
 OWINGS, MD  
 US 20736  
 Contact: LESLIE SNURR  
 LSNURR@KGE.COM  
 T: (410)257-5225  
 F: (410)257-5227

To discuss this sample report, contact Customer Service at 1-800-237-1369.

\* - Denotes test methods that are outside of the ISO 17025 scope of accreditation.

Statements of conformity to specifications are based on the simple acceptance decision rule (JCGM 106:2012)