**WEAR** CONTAMINATION **FLUID CONDITION**  **NORMAL NORMAL NORMAL** 

[SPM688077]

**VOLVO A60H 340136** 

Bogie/Center Axle

RECOMMENDATION	Test	UOM	Method	Limit/Abn	Current	History1	History2
Resample at the next service interval to monitor.	Sample Number	00	Client Info		VCP436189		
	Sample Date		Client Info		16 Mar 2024		
	Machine Age	hrs	Client Info		14660		
	Oil Age	hrs	Client Info		0		
	Filter Age	hrs	Client Info		0		
	Oil Changed		Client Info		Changed		
	Filter Changed		Client Info		Not Changd		
	Sample Status				NORMAL		
WEAR	Iron	ppm	ASTM D5185m	>500	184		
All component wear rates are normal.	Chromium	ppm	ASTM D5185m	>10	3		
	Nickel	ppm	ASTM D5185m	>10	<1		
	Titanium	ppm	ASTM D5185m		0		
	Silver	ppm	ASTM D5185m		0		
	Aluminum	ppm	ASTM D5185m	>25	0		
	Lead	ppm	ASTM D5185m		0		
	Copper	ppm	ASTM D5185m		<1		
	Tin	ppm	ASTM D5185m	>10	0		
	Vanadium	ppm	ASTM D5185m	NONE	0		
	White Metal	scalar	*Visual	NONE	NONE		
	Yellow Metal	scalar	*Visual	NONE	NONE		
CONTAMINATION	Silicon	ppm	ASTM D5185m	>75	3		
There is no indication of any contamination in the fluid.	Potassium	ppm	ASTM D5185m	>20	2		
	Water		WC Method	>0.2	NEG		
	Silt	scalar	*Visual	NONE	MODER		
	Debris	scalar	*Visual	NONE	NONE		
	Sand/Dirt	scalar	*Visual	NONE	NONE		
	Appearance	scalar	*Visual	NORML	NORML		
	Odor	scalar	*Visual	NORML	NORML		
	Emulsified Water	scalar	*Visual	>0.2	NEG		
FLUID CONDITION	Sodium	ppm	ASTM D5185m	>170	5		
The condition of the fluid is acceptable for the time in service.	Boron	ppm	ASTM D5185m	400	245		
	Barium	ppm	ASTM D5185m	200	0		
	Molybdenum	ppm	ASTM D5185m	12	1		
	Manganese	ppm	ASTM D5185m		6		
	Magnesium	ppm	ASTM D5185m		0		
	Calcium	ppm	ASTM D5185m		40		
	Phosphorus	ppm	ASTM D5185m	1650	2335		
	Zinc	ppm	ASTM D5185m		19		
	Sulfur	ppm	ASTM D5185m	22500	31198		





Certificate L2367

Laboratory Sample No.

: VCP436189 Lab Number : 06154890 Unique Number : 10990313 Test Package : MOB 1

: WearCheck USA - 501 Madison Ave., Cary, NC 27513 Received : 19 Apr 2024 **Tested** : 22 Apr 2024 Diagnosed

: 24 Apr 2024 - Sean Felton

1685 N STATE RTE 50 BOURBONNAIS, IL US 60914 Contact: M. POZAN

**BELSON STEEL** 

mpozan@belsonsteel.com T: (815)932-7416

To discuss this sample report, contact Customer Service at 1-800-237-1369.

\* - Denotes test methods that are outside of the ISO 17025 scope of accreditation. Statements of conformity to specifications are based on the simple acceptance decision rule (JCGM 106:2012)

Report Id: BELBOU [WUSCAR] 06154890 (Generated: 04/24/2024 08:57:08) Rev: 1