WEAR CONTAMINATION FLUID CONDITION

NORMAL NORMAL

Area

[702244 ALTA RENTS]

VOLVO A30G 753626

Transmission (Auto)

VOLVO AUTOMATIC TRANSMISSION FLUID AT102 (--- GAL)

VOLVO AUTOMATIC TRANSMISSION FLUID AT102 (GAL)							
RECOMMENDATION	Test	UOM	Method	Limit/Abn	Current	History1	History2
Resample at the next service interval to monitor.	Sample Number		Client Info		VCP451309		
	Sample Date		Client Info		18 Apr 2024		
	Machine Age	hrs	Client Info		727		
	Oil Age	hrs	Client Info		0		
	Filter Age	hrs	Client Info		0		
	Oil Changed		Client Info		Not Changd		
	Filter Changed		Client Info		Not Changd		
	Sample Status				NORMAL		
WEAR	Iron	ppm	ASTM D5185m	>160	22		
All component wear rates are normal.	Chromium	ppm	ASTM D5185m		<1		
	Nickel	ppm	ASTM D5185m		3		
	Titanium	ppm	ASTM D5185m		0		
	Silver	ppm	ASTM D5185m	>5	0		
	Aluminum	ppm	ASTM D5185m		12		
	Lead	ppm	ASTM D5185m	>50	<1		
	Copper	ppm	ASTM D5185m	>225	28		
	Tin	ppm	ASTM D5185m	>10	4		
	Vanadium	ppm	ASTM D5185m		<1		
	White Metal	scalar	*Visual	NONE	NONE		
	Yellow Metal	scalar	*Visual	NONE	NONE		
CONTAMINATION	Silicon	ppm	ASTM D5185m	> 20	13		
There is no indication of any contamination in the fluid.	Potassium	ppm	ASTM D5185m		4		
	Water	ррпп	WC Method		NEG		
	Silt	scalar	*Visual	NONE	NONE		
	Debris	scalar	*Visual	NONE	NONE		
	Sand/Dirt	scalar	*Visual	NONE	NONE		
	Appearance	scalar	*Visual	NORML	NORML		
	Odor	scalar	*Visual	NORML	NORML		
	Emulsified Water	scalar	*Visual	>0.1	NEG		
FLUID CONDITION	Sodium	nnm	ASTM D5185m		4		
	Boron	ppm	ASTM D5185m	197	79		
The condition of the fluid is acceptable for the time in service.	Barium	ppm	ASTM D5185m		0		
	Molybdenum	ppm	ASTM D5185m		0		
	Manganese	ppm	ASTM D5185m		3		
	Magnesium	ppm	ASTM D5185m		<1		
	Calcium	ppm	ASTM D5185m		73		
	Phosphorus	ppm	ASTM D5185m		183		
	Zinc	ppm	ASTM D5185m		6		
	Sulfur	ppm	ASTM D5185m	1336	2009		
	Visc @ 40°C	cSt	ASTM D445	35.3	28.8		





Certificate L2367

Laboratory Sample No.

: VCP451309 Lab Number : 06156486 Unique Number: 10991909 Test Package : MOB 1

: WearCheck USA - 501 Madison Ave., Cary, NC 27513 Received **Tested**

: 22 Apr 2024 : 23 Apr 2024 Diagnosed : 24 Apr 2024 - Jonathan Hester

ALTA EQUIPMENT/FLAGLER CONSTRUCTION EQUIPMENT LLC 8418 PALM RIVER ROAD

TAMPA, FL US 33619 Contact: KENNY HANEY

khaney@flaglerce.com

To discuss this sample report, contact Customer Service at 1-800-237-1369.

* - Denotes test methods that are outside of the ISO 17025 scope of accreditation. Statements of conformity to specifications are based on the simple acceptance decision rule (JCGM 106:2012)

T: (813)630-0077 F: (813)630-2233