

IS4937 WM] Machine Id VOLVO L90H 626204 Component Rear Axle Fluid VOLVO WB 102 (--- GAL)

## RECOMMENDATION

Resample at the next service interval to monitor.

## **WEAR**

All component wear rates are normal.

## CONTAMINATION

There is no indication of any contamination in the oil.

## FLUID CONDITION

The condition of the oil is acceptable for the time in service.

Test	UOM	Method	Limit/Abn	Current	History1	History2
Sample Number		Client Info		VCP430347		
Sample Date		Client Info		07 May 2024		
Machine Age	hrs	Client Info		1435		
Oil Age	hrs	Client Info		0		
Filter Age	hrs	Client Info		0		
Oil Changed		Client Info		Changed		
Filter Changed		Client Info		N/A		
Sample Status				NORMAL		
Iron	ppm	ASTM D5185m	>300	<b>5</b> 36		
Chromium	ppm	ASTM D5185m	>10	4		
Nickel	ppm	ASTM D5185m	>4	1		
Titanium		ASTM D5185m	24	0		
Silver	ppm	ASTM D5185m		0		
Aluminum	ppm	ASTM D5185m	>15	0 <1		
Lead	ppm	ASTM D5185m	>15	2		
Copper	ppm	ASTM D5185m	>200	33		
Tin	ppm	ASTM D5185m	>15	3		
Vanadium	ppm	ASTM D5185m	>10	0		
White Metal	ppm scalar	*Visual	NONE	NONE		
				-		
Yellow Metal	scalar	*Visual	NONE	NONE		
Silicon	ppm	ASTM D5185m	>75	20		
Potassium	ppm	ASTM D5185m	>20	1		
Water		WC Method	>0.2	NEG		
Silt	scalar	*Visual	NONE	MODER		
Debris	scalar	*Visual	NONE	NONE		
Sand/Dirt	scalar	*Visual	NONE	NONE		
Appearance	scalar	*Visual	NORML	NORML		
Odor	scalar	*Visual	NORML	NORML		
Emulsified Water	scalar	*Visual	>0.2	NEG		
Sodium	ppm	ASTM D5185m		11		
Boron	ppm	ASTM D5185m		134		
Barium	ppm	ASTM D5185m		<1		
Molybdenum	ppm	ASTM D5185m		9		
Manganese	ppm	ASTM D5185m		9 10		
Magnesium	ppm	ASTM D5185m		13		
Calcium	ppm	ASTM D5185m		3937		
Phosphorus	ppm	ASTM D5185m		1389		
Zinc	ppm	ASTM D5185m		1705		
2.110	PPIII			5404		

Sulfur

Visc @ 40°C

ASTM D5185m

ASTM D445 55


ppm


cSt


Contact/Location: JIM STRIGLE - VOLVO0142

5121

40.3







Contact/Location: JIM STRIGLE - VOLVO0142 Page 2 of 2

Mav7/24

SYRACUSE, NY

T: (315)437-2611

F: (315)434-9471

US 13206