

VOLVO A25G 742179

{not provided} (--- GAL)

RECOMMENDATION

Resample at the next service interval to monitor. Please specify the brand, type, and viscosity of the oil on your next sample.

WEAR

All component wear rates are normal.

CONTAMINATION

There is no indication of any contamination in the oil.

FLUID CONDITION

The condition of the oil is acceptable for the time in service.

Test	UOM	Method	Limit/Abn	Current	History1	History2
Sample Number		Client Info		ASC0003005		
Sample Date		Client Info		27 Apr 2024		
Machine Age	hrs	Client Info		2183		
Oil Age	hrs	Client Info		0		
Filter Age	hrs	Client Info		0		
Oil Changed		Client Info		N/A		
Filter Changed		Client Info		N/A		
Sample Status				NORMAL		
Iron	ppm	ASTM D5185m	>200	75		
Chromium	ppm	ASTM D5185m	>10	<1		
Nickel	ppm	ASTM D5185m	>10	<1		
Titanium	ppm	ASTM D5185m	-	0		
Silver	ppm	ASTM D5185m		0		
Aluminum	ppm	ASTM D5185m		0		
Lead	ppm	ASTM D5185m		0		
Copper	ppm	ASTM D5185m		5		
Tin	ppm	ASTM D5185m		0		
Vanadium	ppm	ASTM D5185m		0		
White Metal	scalar	*Visual	NONE	NONE		
Yellow Metal	scalar	*Visual	NONE	NONE		
				• • • • • • • • • • • • • • • • • • • •		
Silicon	ppm	ASTM D5185m	00	2		
Potassium	ppm	ASTM D5185m	>20	<1		
Water						
0.11		WC Method	>0.2	NEG		
Silt	scalar	*Visual	NONE	NONE		
Debris	scalar	*Visual *Visual	NONE	NONE		
Debris Sand/Dirt	scalar scalar	*Visual *Visual *Visual	NONE NONE NONE	NONE NONE NONE		
Debris Sand/Dirt Appearance	scalar scalar scalar	*Visual *Visual *Visual *Visual	NONE NONE NORML	NONE NONE NONE NORML		
Debris Sand/Dirt Appearance Odor	scalar scalar scalar scalar	*Visual *Visual *Visual *Visual *Visual	NONE NONE NORML NORML	NONE NONE NORML NORML	 	
Debris Sand/Dirt Appearance	scalar scalar scalar	*Visual *Visual *Visual *Visual	NONE NONE NORML	NONE NONE NONE NORML		
Debris Sand/Dirt Appearance Odor	scalar scalar scalar scalar	*Visual *Visual *Visual *Visual *Visual	NONE NONE NORML NORML	NONE NONE NORML NORML	 	
Debris Sand/Dirt Appearance Odor Emulsified Water	scalar scalar scalar scalar scalar	*Visual *Visual *Visual *Visual *Visual *Visual	NONE NONE NORML NORML	NONE NONE NORML NORML NEG	 	
Debris Sand/Dirt Appearance Odor Emulsified Water Sodium	scalar scalar scalar scalar scalar ppm	*Visual *Visual *Visual *Visual *Visual *Visual ASTM D5185m	NONE NONE NORML NORML	NONE NONE NORML NORML NEG 3		
Debris Sand/Dirt Appearance Odor Emulsified Water Sodium Boron	scalar scalar scalar scalar scalar ppm ppm	*Visual *Visual *Visual *Visual *Visual *Visual ASTM D5185m ASTM D5185m	NONE NONE NORML NORML	NONE NONE NORML NORML NEG 3 284		
Debris Sand/Dirt Appearance Odor Emulsified Water Sodium Boron Barium	scalar scalar scalar scalar scalar ppm ppm	*Visual *Visual *Visual *Visual *Visual ASTM D5185m ASTM D5185m	NONE NONE NORML NORML	NONE NONE NORML NORML NEG 3 284 0		
Debris Sand/Dirt Appearance Odor Emulsified Water Sodium Boron Barium Molybdenum	scalar scalar scalar scalar scalar ppm ppm ppm	*Visual *Visual *Visual *Visual *Visual *Visual ASTM D5185m ASTM D5185m ASTM D5185m	NONE NONE NORML NORML	NONE NONE NORML NORML NEG 3 284 0 <1		
Debris Sand/Dirt Appearance Odor Emulsified Water Sodium Boron Barium Molybdenum Manganese	scalar scalar scalar scalar ppm ppm ppm ppm	*Visual *Visual *Visual *Visual *Visual *Visual ASTM D5185m ASTM D5185m ASTM D5185m ASTM D5185m	NONE NONE NORML NORML	NONE NONE NORML NORML NEG 3 284 0 <1 3		
Debris Sand/Dirt Appearance Odor Emulsified Water Sodium Sodium Baron Barium Molybdenum Manganese	scalar scalar scalar scalar ppm ppm ppm ppm ppm	*Visual *Visual *Visual *Visual *Visual *Visual ASTM D5185m ASTM D5185m ASTM D5185m ASTM D5185m ASTM D5185m	NONE NONE NORML NORML	NONE NONE NORML NORML NEG 3 284 0 <1 3 0		

Sulfur

Visc @ 40°C

ppm

cSt


ASTM D5185m


ASTM D445

Contact/Location: CORY PENLAND - VOLVO1672

31932

53.0





160 - ASCENDUM MACHINERY INC - MILLS RIVER : WearCheck USA - 501 Madison Ave., Cary, NC 27513 :09 May 2024 215 FANNING FIELDS RD : 14 May 2024 MILLS RIVER, NC US 28759 Contact: CORY PENLAND cory.penland@ascendummachinery.com T: (828)687-0620 F: (828)687-0622



Unique Number : 11020358 Diagnosed : 15 May 2024 - Don Baldridge Test Package : CONST Certificate L2367 To discuss this sample report, contact Customer Service at 1-800-237-1369. * - Denotes test methods that are outside of the ISO 17025 scope of accreditation. Statements of conformity to specifications are based on the simple acceptance decision rule (JCGM 106:2012)

Received

Tested

Laboratory

Sample No.

Lab Number : 06174305

: ASC0003005

Contact/Location: CORY PENLAND - VOLVO1672 Page 2 of 2