NORMAL NORMAL NORMAL


Area


[SWO-071569]
Wachine Id
VOLVO A45G 353092
Component

Coolant

VOLVO COOLANT VCS (YELLOW) (--- GAL)

VOLVO GOCIANT VOS (TELEGW) (GAE)							
RECOMMENDATION	Test	UOM	Method	Limit/Abn	Current	History1	History2
No corrective action is recommended at this time. The fluid is suitable for further service.	Sample Number		Client Info		VCP453712	VCP447540	VCP432850
	Sample Date		Client Info		02 May 2024	03 Jan 2024	19 Sep 2023
	Machine Age	hrs	Client Info		3022	2545	2012
	Oil Age	hrs	Client Info		0	0	0
	Oil Changed		Client Info		Not Changd	Not Changd	Not Changd
	Sample Status				NORMAL	NORMAL	NORMAL
CORROSION	Total Dissolved Solids				227.0	267.5	266.5
	Coolant Appearance		*Visual	Clear	normal	normal	normal
CONTAMINANTS	Boiling Point	°C	WC Method		223		
There is no indication of any contamination in the coolant.	Specific Gravity		*ASTM D1298		1.060	1.060	1.060
	рН	Scale 0-14	ASTM D1287		7.28	7.32	7.44
	Nitrites	ppm	AP-053:2009		NT	NT	NT
	Reserve Alkalinity	Scale 0-20	*ASTM D1121				
	Percentage Glycol	%	ASTM D3321		44.0	44.2	44.1
	Freezing Point	°F	ASTM D3321		-21	-21	-21
	Carboxylate				fail	fail	fail
	Coolant Color		*Visual		Yllow	Yllow	Yllow







Laboratory Sample No.

Unique Number : 11020621

: VCP453712 Lab Number : 06174568

рΗ

Received **Tested** Diagnosed

Statements of conformity to specifications are based on the simple acceptance decision rule (JCGM 106:2012)

: 16 May 2024 Test Package : COOL- (Additional Tests: BoilingPoint, COOL, GlycolType)

: 09 May 2024

: 16 May 2024 - Jonathan Hester

Nitrites

> SAIIA CONSTRUCTION LLC 4400 LEWISBURG RD BIRMINGHAM, AL

US 35207 Contact: STEPHANI BRITTON

F: (205)943-2269

Certificate L2367 sbritton@saiia.com;doug.bogart@wearcheck.com To discuss this sample report, contact Customer Service at 1-800-237-1369. * - Denotes test methods that are outside of the ISO 17025 scope of accreditation. T: (205)943-2268