
**WEAR** CONTAMINATION **FLUID CONDITION** 

**NORMAL ABNORMAL ABNORMAL** 

Machine Id

## PACCAR 846-4112

Diesel Engine							
MOBIL DELVAC 1300 SUPER15W40 (24 QTS)							
RECOMMENDATION	Test	UOM	Method	Limit/Abn	Current	History1	History2
RECOMMENDATION	Sample Number	OOW	Client Info	LIIIIUADII	RPL0019334		RPL0015533
We recommend that you drain the oil from the component if this has not already been done. We recommend an early resample to monitor this condition.	Sample Date		Client Info		18 Apr 2024	31 Jan 2024	05 Oct 2023
	Machine Age	mls	Client Info		157747	152855	146447
	Oil Age	mls	Client Info		4889	12791	6383
	Filter Age	mls	Client Info		4889	12791	6383
	Oil Changed		Client Info		Not Changd	Changed	Filtered
	Filter Changed		Client Info		Not Changd	Changed	Not Changd
	Sample Status				ABNORMAL	ABNORMAL	ABNORMAL
WEAR	Iron	ppm	ASTM D5185m	>100	13	21	8
	Chromium	ppm	ASTM D5185m		0	<1	0
Metal levels are typical for a new component breaking in.	Nickel	ppm	ASTM D5185m		0	<1	0
	Titanium	ppm	ASTM D5185m		0	<1	0
	Silver	ppm	ASTM D5185m	>3	0	0	0
	Aluminum	ppm	ASTM D5185m		5	3	1
	Lead	ppm	ASTM D5185m	>40	<1	1	0
	Copper	ppm	ASTM D5185m	>330	0	4	3
	Tin	ppm	ASTM D5185m	>15	0	<1	0
	Vanadium	ppm	ASTM D5185m		0	0	0
	White Metal	scalar	*Visual	NONE	NONE	NONE	NONE
	Yellow Metal	scalar	*Visual	NONE	NONE	NONE	NONE
CONTAMINATION	Silicon	ppm	ASTM D5185m	<b>&gt;25</b>	4	3	2
CONTAININATION	Potassium	ppm	ASTM D5185m		9	7	0
There is a moderate amount of fuel present in the oil. Tests confirm the presence of fuel in the oil.	Fuel	%	ASTM D3524	>5	<u> </u>	7.2	<u>△</u> 5.6
	Water	/0	WC Method		NEG	NEG	NEG
	Glycol		WC Method	7 U.L	NEG	NEG	NEG
	Soot %	%	*ASTM D7844	>3	0.3	0.5	0.3
	Nitration	Abs/cm	*ASTM D7624	>20	9.0	11.2	7.9
	Sulfation	Abs/.1mm	*ASTM D7415	>30	20.6	22.8	20.0
	Silt	scalar	*Visual	NONE	NONE	NONE	NONE
	Debris	scalar	*Visual	NONE	NONE	NONE	NONE
	Sand/Dirt	scalar	*Visual	NONE	NONE	NONE	NONE
	Appearance	scalar	*Visual	NORML	NORML	NORML	NORML
	Odor	scalar	*Visual	NORML	NORML	NORML	NORML
	Emulsified Water	scalar	*Visual	>0.2	NEG	NEG	NEG
FLUID CONDITION	Sodium	ppm	ASTM D5185m		<1	0	1
	Boron	ppm	ASTM D5185m	0	4	1	1
The BN result indicates that there is suitable alkalinity remaining in the oil. Fuel is present in the oil and is lowering the viscosity. The oil is no longer serviceable due to the presence of contaminants.	Barium	ppm	ASTM D5185m	0	0	<1	0
	Molybdenum	ppm	ASTM D5185m	0	55	53	54
	Manganese	ppm	ASTM D5185m		<1	<1	<1
	Magnesium	ppm	ASTM D5185m	0	886	797	796
	Calcium	ppm	ASTM D5185m		1002	956	941
	Phosphorus	ppm	ASTM D5185m		1005	888	856
	Zinc	ppm	ASTM D5185m		1157	1095	1041
	Sulfur	ppm	ASTM D5185m		3434	3102	2645
	Oxidation	Abs/.1mm	*ASTM D7414		18.5	23.4	17.4
	Base Number (BN)				8.6	6.0	8.8
	Visc @ 100°C	cSt	ASTM D445	14	11.4	<u> </u>	<u>12.0</u>





Certificate L2367

Laboratory Sample No.

: WearCheck USA - 501 Madison Ave., Cary, NC 27513 : RPL0019334 Lab Number : 06175331

Received **Tested** Unique Number: 11021384 Diagnosed

: 15 May 2024 : 15 May 2024 - Wes Davis Test Package: FLEET (Additional Tests: PercentFuel)

: 10 May 2024

RTL PACLEASE - 7006 - Pico Rivera 7837 Telegraph Rd

Pico Rivera, CA US 90660 Contact: GERARDO CARROLA

To discuss this sample report, contact Customer Service at 1-800-237-1369.

carrolag@rushenterprises.com T:

\* - Denotes test methods that are outside of the ISO 17025 scope of accreditation. Statements of conformity to specifications are based on the simple acceptance decision rule (JCGM 106:2012)

Report Id: PAC7006 [WUSCAR] 06175331 (Generated: 05/15/2024 14:48:15) Rev: 1

F: