CORROSION
CONTAMINANTS
COOLANT CONDITION

NORMAL NORMAL NORMAL


Machine Id


JOHN DEERE 85G 1FF085GXHLJ021862

Component Coolant

{not provided} (--- GAL)

RECOMMENDATION	Test	UOM	Method	Limit/Abn	Current	History1	History2
The fluid is suitable for further service.	Sample Number		Client Info		JR0205359		
	Sample Date		Client Info		08 May 2024		
	Machine Age	hrs	Client Info		1205		
	Oil Age	hrs	Client Info		1205		
	Oil Changed		Client Info		Not Changd		
	Sample Status				NORMAL		
CORROSION	Total Dissolved Solids				526.0		
	Coolant Appearance		*Visual	Clear	normal		
CONTAMINANTS	Boiling Point	°C	WC Method		226		
There is no indication of any contamination in the coolant.	Specific Gravity		*ASTM D1298		1.069		
	рН	Scale 0-14	ASTM D1287		7.80		
	Nitrites	ppm	AP-053:2009		NT		
	Reserve Alkalinity	Scale 0-20	*ASTM D1121				
	Percentage Glycol	%	ASTM D3321		51.0		
	Freezing Point	°F	ASTM D3321		-38		
	Carboxylate				n/a		
	Coolant Color		*Visual		Green		







Laboratory Sample No.

Lab Number : 06176017 Unique Number : 11022070

: WearCheck USA - 501 Madison Ave., Cary, NC 27513 : JR0205359

Received **Tested** Diagnosed

: 16 May 2024

: 10 May 2024

: 16 May 2024 - Jonathan Hester Test Package : COOL- (Additional Tests: BoilingPoint, COOL, GlycolType, PQ) 9550 STATESVILLE ROAD CHARLOTTE, NC US 28269

JRE - CHARLOTTE

Contact: GARRETT FRICK gfrick@jamesriverequipment.com

To discuss this sample report, contact Customer Service at 1-800-237-1369. * - Denotes test methods that are outside of the ISO 17025 scope of accreditation. Statements of conformity to specifications are based on the simple acceptance decision rule (JCGM 106:2012)

F: (704)596-6198