

Machine Id WL102 (S/N 6ZS01471) Component Hydraulic System Fluid DURALENE Trans-Flo UTF (--- QTS)

RECOMMENDATION

Resample at the next service interval to monitor.

WEAR

All component wear rates are normal.

CONTAMINATION

There is no indication of any contamination in the oil.

FLUID CONDITION

The condition of the oil is acceptable for the time in service.

Test	UOM	Method	Limit/Abn	Current	History1	History2
Sample Number		Client Info		DC0024017		
Sample Date		Client Info		09 May 2024		
Machine Age	hrs	Client Info		0		
Oil Age	hrs	Client Info		0		
Filter Age	hrs	Client Info		0		
Oil Changed		Client Info		N/A		
Filter Changed		Client Info		N/A		
Sample Status				NORMAL		
			00	10		
Iron Obversives	ppm		>20	10		
Chromium	ррп		>10	<1		
NICKEI	ppm	ASTM D5185m	>10	0		
Titanium	ppm	ASTM D5185m		<1		
Silver	ppm	ASTM D5185m	10	<1		
Aluminum	ppm	ASTM D5185m	>10	3		
Lead	ppm	ASTM D5185m	>10	2		
Copper	ppm	ASTM D5185m	>75	15		
Tin	ppm	ASTM D5185m	>10	0		
Vanadium	ppm	ASTM D5185m		0		
White Metal	scalar	*Visual	NONE	NONE		
Yellow Metal	scalar	*Visual	NONE	NONE		
Silicon	maa	ASTM D5185m	>20	9		
Potassium	ppm	ASTM D5185m	>20	2		
Water	1-1-	WC Method	>0.1	NEG		
Silt	scalar	*Visual	NONE	NONE		
Debris	scalar	*Visual	NONE	NONE		
Sand/Dirt	scalar	*Visual	NONE	NONE		
Appearance	scalar	*Visual	NORML	NORML		
Odor	scalar	*Visual	NORML	NORML		
Emulsified Water	scalar	*Visual	>0.1	NEG		
Sodium	ppm	ASTM D5185m		10		
Boron	ppm	ASTM D5185m		67		
Barium	ppm	ASTM D5185m		0		
Molybdenum	ppm	ASTM D5185m		3		
Manganese	ppm	ASTM D5185m		<1		
Magnesium	ppm	ASTM D5185m		0		
Calcium	ppm	ASTM D5185m		2550		
Phosphorus	ppm	ASTM D5185m		869		
Zinc	ppm	ASTM D5185m		1090		
Sulfur	ppm	ASTM D5185m		3588		
Visc @ 40°C	cSt	ASTM D445		43.1		

Contact/Location: JACOB FLAUGHER - MAGUNI

WEAR NORMAL CONTAMINATION NORMAL FLUID CONDITION NORMAL





Contact/Location: JACOB FLAUGHER - MAGUNI Page 2 of 2