**WEAR CONTAMINATION FLUID CONDITION**  **NORMAL NORMAL NORMAL** 

## [HERC RENTALS] VOLVO L70H 625245

**Transmission (Auto)** 

VOLVO AUTOMATIC TRANS						\	
RECOMMENDATION	Test	UOM	Method	Limit/Abn	Current	History1	History2
Resample at the next service interval to monitor.	Sample Number		Client Info		VCP432049		
	Sample Date		Client Info		21 Apr 2024		
	Machine Age	hrs	Client Info		773		
	Oil Age	hrs	Client Info		0		
	Filter Age	hrs	Client Info		0		
	Oil Changed		Client Info		Not Changd		
	Filter Changed		Client Info		Not Changd		
	Sample Status				NORMAL		
WEAR	Iron	ppm	ASTM D5185m	>160	94		
All component wear rates are normal.	Chromium	ppm	ASTM D5185m	>5	<1		
	Nickel	ppm	ASTM D5185m	>5	<1		
	Titanium	ppm	ASTM D5185m		<1		
	Silver	ppm	ASTM D5185m	>5	<1		
	Aluminum	ppm	ASTM D5185m	>50	1		
	Lead	ppm	ASTM D5185m	>50	<1		
	Copper	ppm	ASTM D5185m	>225	6		
	Tin	ppm	ASTM D5185m	>10	<1		
	Vanadium	ppm	ASTM D5185m		0		
	White Metal	scalar	*Visual	NONE	NONE		
	Yellow Metal	scalar	*Visual	NONE	NONE		
CONTAMINATION	Silicon	ppm	ASTM D5185m	>20	11		
There is no indication of any contamination in the fluid.	Potassium	ppm	ASTM D5185m		3		
	Water				NEG		
	Silt	scalar	*Visual	NONE	NONE		
	Debris	scalar	*Visual	NONE	NONE		
	Sand/Dirt	scalar	*Visual	NONE	NONE		
	Appearance	scalar	*Visual	NORML	NORML		
	Odor	scalar	*Visual	NORML	NORML		
	Emulsified Water	scalar	*Visual	>0.1	NEG		
FLUID CONDITION	Sodium	ppm	ASTM D5185m		3		
The condition of the fluid is acceptable for the time in service.	Boron	ppm	ASTM D5185m	187	85		
	Barium	ppm	ASTM D5185m	0.0	2		
	Molybdenum	ppm	ASTM D5185m	0.0	<1		
	Manganese	ppm	ASTM D5185m	0.0	6		
	Magnesium	ppm	ASTM D5185m	6.8	2		
	Calcium	ppm	ASTM D5185m	215	79		
	Phosphorus	ppm	ASTM D5185m	445	185		
	Zinc	ppm	ASTM D5185m	56	28		
	Sulfur	ppm	ASTM D5185m	1336	1808		
	Visc @ 40°C	cSt	ASTM D445	35.3	28.4		





Laboratory Sample No.

: VCP432049 Lab Number : 06188138 Unique Number : 11044890

: WearCheck USA - 501 Madison Ave., Cary, NC 27513

Received **Tested** 

: 22 May 2024 : 23 May 2024 Diagnosed

: 23 May 2024 - Wes Davis

ALTA EQUIPMENT/FLAGLER CONSTRUCTION EQUIPMENT LLC 8418 PALM RIVER ROAD

TAMPA, FL US 33619 Contact: KENNY HANEY

khaney@flaglerce.com

T: (813)630-0077

F: (813)630-2233

Test Package : MOB 1 Certificate L2367 To discuss this sample report, contact Customer Service at 1-800-237-1369.

\* - Denotes test methods that are outside of the ISO 17025 scope of accreditation. Statements of conformity to specifications are based on the simple acceptance decision rule (JCGM 106:2012)