

DAVE HOLT [PATRICK/502207-5750] Machine Id ONAN L160124932 Genset

VOLVO VDS-4.5 Premium Motor Oil 15W40 (2 GAL)

	····· ' ·····						
RECOMMENDATION	Test	UOM	Method	Limit/Abn	Current	History1	History2
No corrective action is recommended at this time. Resample at the next service interval to monitor.	Sample Number		Client Info		VPA062543		
	Sample Date		Client Info		21 May 2024		
	Machine Age	hrs	Client Info		576		
	Oil Age	hrs	Client Info		0		
	Filter Age	hrs	Client Info		0		
	Oil Changed		Client Info		Changed		
	Filter Changed		Client Info		Changed		
	Sample Status				NORMAL		
					•		
WEAR	Iron	ppm	ASTM D5185m		3		
Metal levels are typical for a new component breaking in.	Chromium	ppm	ASTM D5185m		<1		
	Nickel	ppm	ASTM D5185m	>2	<1		
	Titanium	ppm	ASTM D5185m	_	<1		
	Silver	ppm	ASTM D5185m		<1		
	Aluminum	ppm	ASTM D5185m		1		
	Lead	ppm	ASTM D5185m		<1		
	Copper	ppm	ASTM D5185m		<1		
	Tin	ppm	ASTM D5185m	>15	<1		
	Vanadium	ppm	ASTM D5185m		<1		
	White Metal	scalar	*Visual	NONE	NONE		
	Yellow Metal	scalar	*Visual	NONE	NONE		
CONTAMINATION	Silicon	ppm	ASTM D5185m	>25	8		
There is no indication of any contamination in the oil.	Potassium	ppm	ASTM D5185m	>20	2		
	Fuel		WC Method	>4.0	<1.0		
	Water		WC Method	>0.1	NEG		
	Glycol		WC Method		NEG		
	Soot %	%	*ASTM D7844		0.2		
	Nitration	Abs/cm	*ASTM D7624	>20	6.7		
	Sulfation	Abs/.1mm	*ASTM D7415	>30	19.2		
	Silt	scalar	*Visual	NONE	NONE		
	Debris	scalar	*Visual	NONE	NONE		
	Sand/Dirt	scalar	*Visual	NONE	NONE		
	Appearance	scalar	*Visual	NORML	NORML		
	Odor	scalar	*Visual	NORML	NORML		
	Emulsified Water	scalar	*Visual	>0.1	NEG		
FLUID CONDITION	Sodium	ppm	ASTM D5185m		3		
	Boron	ppm	ASTM D5185m		74		
The BN result indicates that there is suitable alkalinity remaining in the oil. The condition of the oil is suitable for further service.	Barium	ppm	ASTM D5185m		0		
	Molybdenum	ppm	ASTM D5185m		42		
	Manganese	ppm	ASTM D5185m		0		
	Magnesium	ppm	ASTM D5185m		771		
	Calcium		ASTM D5185m		1184		
		ppm	ASTM D5185m				
	Phosphorus	ppm			718		
	Zinc	ppm	ASTM D5185m		889		
	Sulfur	ppm	ASTM D5185m	05	2633		
	Oxidation	Abs/.1mm	*ASTM D7414	>25	15.0		
	Base Number (BN)	mg KOH/g	ASTM D2896		8.9		

Visc @ 100°C cSt

ASTM D445

13.9



Laboratory : WearCheck USA - 501 Madison Ave., Cary, NC 27513 Endor Marine LLC - Coastal Marine - 152124 Sample No. Received 4300 11th Ave. NW : VPA062543 : 23 May 2024 Lab Number : 06188741 Tested SEATTLE, WA : 24 May 2024 Unique Number : 11045493 Diagnosed : 28 May 2024 - Sean Felton US 98107 Test Package : MOB 1 (Additional Tests: TBN) Contact: WILLOW YANARELLA Certificate L2367 To discuss this sample report, contact Customer Service at 1-800-237-1369. service@coastalmarineengine.com * - Denotes test methods that are outside of the ISO 17025 scope of accreditation. T: (206)784-3703 Statements of conformity to specifications are based on the simple acceptance decision rule (JCGM 106:2012) F: (206)784-8823

Ē