WEAR CONTAMINATION **FLUID CONDITION**

NORMAL NORMAL NORMAL

Machine Id

BUS 44
Component
Diesel Engine
Fluid

RECOMMENDATION	Test	UOM	Method	Limit/Abn	Current	History1	History2
Resample at the next service interval to monitor. Please specify the component make and model with your next sample.	Sample Number		Client Info		WC0867980		
	Sample Date		Client Info		10 May 2024		
	Machine Age	mls	Client Info		36936		
	Oil Age	mls	Client Info		0		
	Filter Age	mls	Client Info		0		
	Oil Changed		Client Info		Not Changd		
	Filter Changed		Client Info		Not Changd		
	Sample Status				NORMAL		
WEAR	Iron	ppm	ASTM D5185m		25		
Metal levels are typical for a new component breaking in.	Chromium	ppm	ASTM D5185m		1		
	Nickel	ppm	ASTM D5185m	>4	<1		
	Titanium	ppm	ASTM D5185m		<1		
	Silver	ppm	ASTM D5185m		<1		
	Aluminum	ppm	ASTM D5185m		10		
	Lead	ppm	ASTM D5185m	-	<1		
	Copper	ppm	ASTM D5185m		2		
	Tin	ppm	ASTM D5185m	>15	1		
	Vanadium	ppm	ASTM D5185m		<1		
	White Metal	scalar	*Visual	NONE	NONE		
	Yellow Metal	scalar	*Visual	NONE	NONE		
ONTAMINATION	Silicon	ppm	ASTM D5185m	>25	6		
There is no indication of any contamination in the oil.	Potassium	ppm	ASTM D5185m	>20	7		
	Fuel		WC Method	>5	<1.0		
	Water		WC Method	>0.2	NEG		
	Glycol		WC Method		NEG		
	Soot %	%	*ASTM D7844	>3	0.8		
	Nitration	Abs/cm	*ASTM D7624	>20	9.0		
	Sulfation	Abs/.1mm	*ASTM D7415	>30	20.2		
	Silt	scalar	*Visual	NONE	NONE		
	Debris	scalar	*Visual	NONE	NONE		
	Sand/Dirt	scalar	*Visual	NONE	NONE		
	Appearance	scalar	*Visual	NORML	NORML		
	Odor	scalar	*Visual	NORML	NORML		
	Emulsified Water	scalar	*Visual	>0.2	NEG		
LUID CONDITION	Sodium	nnm	ASTM D5185m		2		
LOID CONDITION	Boron	ppm	ASTM D5165III		10		
The BN result indicates that there is suitable alkalinity remaining in the oil. The condition of the oil is suitable for further service.	Barium	ppm	ASTM D5185m		0		
	Molybdenum	ppm	ASTM D5185m		68		
	Manganese	ppm	ASTM D5185m		<1		
	Magnesium	ppm	ASTM D5185m		875		
	Calcium	ppm	ASTM D5185m		1293		
	Phosphorus	ppm	ASTM D5185m		1005		
	Zinc	ppm	ASTM D5185m		1317		
	Sulfur	ppm	ASTM D5185m		3476		
	Oxidation	Abs/.1mm	*ASTM D3163111	>25	15.7		
	Base Number (BN)				8.3		
	Dasc Halliber (DIV)	my Komy	10 HVI D2030	5.0	0.0		





Certificate L2367

Laboratory Sample No.

Lab Number : 06190023 Unique Number : 11046775

Test Package : MOB 1 (Additional Tests: TBN)

: WearCheck USA - 501 Madison Ave., Cary, NC 27513 Received : WC0867980 : 23 May 2024

Tested : 25 May 2024 Diagnosed

: 25 May 2024 - Wes Davis

GOLDSBORO, NC US 27530 Contact: BRANDON BRIGGS

1603 SALEM CHURCH RD

WAYNE CO SCHOOL BUS GARAGE

brandonbriggs@wcps.org

T: F: Statements of conformity to specifications are based on the simple acceptance decision rule (JCGM 106:2012)

To discuss this sample report, contact Customer Service at 1-800-237-1369. * - Denotes test methods that are outside of the ISO 17025 scope of accreditation.