



WEAR	<b>NORMAL</b>
CONTAMINATION	<b>NORMAL</b>
FLUID CONDITION	<b>NORMAL</b>

Machine Id  
**INTERNATIONAL 5012906**  
Component  
**Diesel Engine**  
Fluid  
**VALVOLINE 15W40 (--- GAL)**

### RECOMMENDATION

Resample at the next service interval to monitor.

Test	UOM	Method	Limit/Abn	Current	History1	History2
Sample Number		Client Info		<b>IL0036586</b>	IL0035061	IL0034292
Sample Date		Client Info		<b>06 May 2024</b>	06 Feb 2024	01 Nov 2023
Machine Age	mls	Client Info		<b>331940</b>	319824	308128
Oil Age	mls	Client Info		<b>0</b>	0	0
Filter Age	mls	Client Info		<b>0</b>	0	0
Oil Changed		Client Info		<b>Changed</b>	Changed	Changed
Filter Changed		Client Info		<b>Changed</b>	Changed	N/A
Sample Status				<b>NORMAL</b>	NORMAL	NORMAL

### WEAR

All component wear rates are normal.

Iron	ppm	ASTM D5185m	>100	<b>26</b>	15	15
Chromium	ppm	ASTM D5185m	>20	<b>&lt;1</b>	<1	<1
Nickel	ppm	ASTM D5185m	>4	<b>0</b>	0	0
Titanium	ppm	ASTM D5185m		<b>0</b>	<1	<1
Silver	ppm	ASTM D5185m	>3	<b>0</b>	<1	0
Aluminum	ppm	ASTM D5185m	>20	<b>9</b>	4	5
Lead	ppm	ASTM D5185m	>40	<b>0</b>	0	0
Copper	ppm	ASTM D5185m	>330	<b>2</b>	1	1
Tin	ppm	ASTM D5185m	>15	<b>0</b>	0	<1
Vanadium	ppm	ASTM D5185m		<b>&lt;1</b>	0	<1
White Metal	scalar	*Visual	NONE	<b>NONE</b>	NONE	NONE
Yellow Metal	scalar	*Visual	NONE	<b>NONE</b>	NONE	NONE

### CONTAMINATION








There is no indication of any contamination in the oil.

Silicon	ppm	ASTM D5185m	>25	<b>6</b>	4	6
Potassium	ppm	ASTM D5185m	>20	<b>&lt;1</b>	4	2
Fuel		WC Method	>5	<b>&lt;1.0</b>	<1.0	1.1
Water		WC Method	>0.2	<b>NEG</b>	NEG	NEG
Glycol		WC Method		<b>NEG</b>	NEG	NEG
Soot %	%	*ASTM D7844	>3	<b>0.7</b>	0.4	0.4
Nitration	Abs/cm	*ASTM D7624	>20	<b>12.0</b>	10.8	10.7
Sulfation	Abs/.1mm	*ASTM D7415	>30	<b>22.3</b>	22.6	21.5
Silt	scalar	*Visual	NONE	<b>NONE</b>	NONE	NONE
Debris	scalar	*Visual	NONE	<b>NONE</b>	NONE	NONE
Sand/Dirt	scalar	*Visual	NONE	<b>NONE</b>	NONE	NONE
Appearance	scalar	*Visual	NORML	<b>NORML</b>	NORML	NORML
Odor	scalar	*Visual	NORML	<b>NORML</b>	NORML	NORML
Emulsified Water	scalar	*Visual	>0.2	<b>NEG</b>	NEG	NEG

### FLUID CONDITION

The BN result indicates that there is suitable alkalinity remaining in the oil. The condition of the oil is suitable for further service.

Sodium	ppm	ASTM D5185m		<b>3</b>	0	2
Boron	ppm	ASTM D5185m	39	<b>31</b>	68	49
Barium	ppm	ASTM D5185m	1	<b>0</b>	25	0
Molybdenum	ppm	ASTM D5185m	49	<b>63</b>	71	92
Manganese	ppm	ASTM D5185m	1	<b>&lt;1</b>	0	<1
Magnesium	ppm	ASTM D5185m	616	<b>780</b>	594	694
Calcium	ppm	ASTM D5185m	1554	<b>1409</b>	1319	1366
Phosphorus	ppm	ASTM D5185m	899	<b>833</b>	859	849
Zinc	ppm	ASTM D5185m	1069	<b>994</b>	983	1028
Sulfur	ppm	ASTM D5185m	2624	<b>2917</b>	2866	2550
Oxidation	Abs/.1mm	*ASTM D7414	>25	<b>21.1</b>	20.1	18.5
Base Number (BN)	mg KOH/g	ASTM D2896	6.9	<b>6.3</b>	5.8	6.3
Visc @ 100°C	cSt	ASTM D445	13.6	<b>12.8</b>	12.7	11.9



Certificate L2367

**Laboratory** : WearCheck USA - 501 Madison Ave., Cary, NC 27513  
**Sample No.** : IL0036586  
**Lab Number** : 06193560  
**Unique Number** : 11050312  
**Test Package** : FLEET

**Received** : 29 May 2024  
**Tested** : 30 May 2024  
**Diagnosed** : 30 May 2024 - Wes Davis

**TAMPA IDEALEASE**  
 5951 ORIENT ROAD  
 TAMPA, FL  
 US 33610-9565  
 Contact: Russ Cook  
 russcook@idealease.com  
 T: (813)626-9285  
 F: (844)270-1356

To discuss this sample report, contact Customer Service at 1-800-237-1369.  
 \* - Denotes test methods that are outside of the ISO 17025 scope of accreditation.  
 Statements of conformity to specifications are based on the simple acceptance decision rule (JCGM 106:2012)